

Company LEW Corporation
 XRF Make Heuresis
 Model Pb200i
 Serial Num. 2128
 Lead concentration units: mg/cm2
 Total Readings: 113
 Action Level 1
 Mode Action Level
 Analytic Mode Paint

All Readings

| Job Id | Reading # | Concentration | Result | Calibration | RTA Present | Date | Time | User | Analytic Mode | Site Address | Area | Unit # | Room | Structure | Member | Substrate | Wall | Location |
|---------|-----------|---------------|----------|-------------|-------------|-----------|----------|-----------------|---------------|--------------|------|--------|---------------------|-----------|-------------|-----------|------|----------|
| 6111213 | 22397 | 1 | | TRUE | FALSE | 6/11/2024 | 12:14 PM | Danny Feliciano | Paint | 4 Brook Rd | | | | | | | | |
| 6111213 | 22398 | 1 | | TRUE | FALSE | 6/11/2024 | 12:15 PM | Danny Feliciano | Paint | 4 Brook Rd | | | | | | | | |
| 6111213 | 22399 | 1 | | TRUE | FALSE | 6/11/2024 | 12:15 PM | Danny Feliciano | Paint | 4 Brook Rd | | | | | | | | |
| 6111213 | 22400 | 0 | | TRUE | FALSE | 6/11/2024 | 12:16 PM | Danny Feliciano | Paint | 4 Brook Rd | | | | | | | | |
| 6111213 | 22401 | 0 | | TRUE | FALSE | 6/11/2024 | 12:16 PM | Danny Feliciano | Paint | 4 Brook Rd | | | | | | | | |
| 6111213 | 22402 | 0 | | TRUE | FALSE | 6/11/2024 | 12:17 PM | Danny Feliciano | Paint | 4 Brook Rd | | | | | | | | |
| 6111213 | 22403 | 0.2 | Negative | FALSE | FALSE | 6/11/2024 | 12:17 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Living Room/Kitchen | Door | --- | Wood | A | |
| 6111213 | 22404 | -0.8 | Negative | FALSE | TRUE | 6/11/2024 | 12:18 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Living Room/Kitchen | Door | Casing | Wood | A | |
| 6111213 | 22405 | -0.4 | Negative | FALSE | TRUE | 6/11/2024 | 12:18 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Living Room/Kitchen | Window | Casing | Wood | A | |
| 6111213 | 22406 | -0.6 | Negative | FALSE | TRUE | 6/11/2024 | 12:19 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Living Room/Kitchen | Window | Sill | Wood | A | |
| 6111213 | 22407 | -0.9 | Negative | FALSE | TRUE | 6/11/2024 | 12:19 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Living Room/Kitchen | Closet | Door | Wood | C | |
| 6111213 | 22408 | -0.1 | Negative | FALSE | FALSE | 6/11/2024 | 12:20 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Living Room/Kitchen | Closet | Door Casing | Wood | C | |
| 6111213 | 22409 | -0.4 | Negative | FALSE | TRUE | 6/11/2024 | 12:20 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Living Room/Kitchen | Room | Baseboard | Wood | C | |
| 6111213 | 22410 | -0.5 | Negative | FALSE | TRUE | 6/11/2024 | 12:21 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Living Room/Kitchen | A/C | Frame | Wood | B | |
| 6111213 | 22411 | -0.3 | Negative | FALSE | TRUE | 6/11/2024 | 12:22 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Living Room/Kitchen | Door | | Wood | D | |
| 6111213 | 22412 | -0.6 | Negative | FALSE | TRUE | 6/11/2024 | 12:22 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Living Room/Kitchen | Window | Casing | Wood | D | |
| 6111213 | 22413 | 0.2 | Negative | FALSE | FALSE | 6/11/2024 | 12:22 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Living Room/Kitchen | Room | Wall | Drywall | D | |
| 6111213 | 22414 | 0.1 | Negative | FALSE | FALSE | 6/11/2024 | 12:23 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Living Room/Kitchen | Room | Wall | Drywall | A | |
| 6111213 | 22415 | 0.1 | Negative | FALSE | FALSE | 6/11/2024 | 12:23 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Living Room/Kitchen | Room | Wall | Drywall | B | |
| 6111213 | 22416 | 0 | Negative | FALSE | FALSE | 6/11/2024 | 12:24 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Living Room/Kitchen | Room | Wall | Drywall | C | |
| 6111213 | 22417 | 0.1 | Negative | FALSE | FALSE | 6/11/2024 | 12:24 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Living Room/Kitchen | Room | Ceiling | Drywall | | |
| 6111213 | 22418 | -0.5 | Negative | FALSE | TRUE | 6/11/2024 | 12:25 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Living Room/Kitchen | Window | Sill | Wood | A | 1 |
| 6111213 | 22419 | -0.8 | Negative | FALSE | TRUE | 6/11/2024 | 12:26 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Foyer/Hall | Door | Casing | Wood | D | |
| 6111213 | 22420 | -0.6 | Negative | FALSE | TRUE | 6/11/2024 | 12:26 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Foyer/Hall | Door | Jamb | Wood | D | |
| 6111213 | 22421 | -0.9 | Negative | FALSE | TRUE | 6/11/2024 | 12:26 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Foyer/Hall | Door | --- | Wood | B | |
| 6111213 | 22422 | -0.4 | Negative | FALSE | TRUE | 6/11/2024 | 12:27 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Foyer/Hall | Room | Baseboard | Wood | C | |
| 6111213 | 22423 | 0.1 | Negative | FALSE | FALSE | 6/11/2024 | 12:27 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Foyer/Hall | Room | Wall | Drywall | C | |
| 6111213 | 22424 | 0.2 | Negative | FALSE | FALSE | 6/11/2024 | 12:28 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Foyer/Hall | Room | Wall | Drywall | B | |
| 6111213 | 22425 | 0.1 | Negative | FALSE | FALSE | 6/11/2024 | 12:28 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Foyer/Hall | Room | Wall | Drywall | D | |
| 6111213 | 22426 | 0 | Negative | FALSE | FALSE | 6/11/2024 | 12:29 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Foyer/Hall | Room | Wall | Drywall | A | |
| 6111213 | 22427 | 0.1 | Negative | FALSE | FALSE | 6/11/2024 | 12:29 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Foyer/Hall | Room | Ceiling | Drywall | | |
| 6111213 | 22428 | -0.6 | Negative | FALSE | TRUE | 6/11/2024 | 12:30 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Foyer/Hall | Closet | Door | Wood | BD | |
| 6111213 | 22429 | -0.7 | Negative | FALSE | TRUE | 6/11/2024 | 12:30 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Foyer/Hall | Closet | Door Casing | Wood | D | |
| 6111213 | 22430 | -0.6 | Negative | FALSE | TRUE | 6/11/2024 | 12:31 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Foyer/Hall | Closet | Door Jamb | Wood | D | |
| 6111213 | 22431 | -0.8 | Negative | FALSE | TRUE | 6/11/2024 | 12:32 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bedroom 1 | Door | | Wood | D | |
| 6111213 | 22432 | -0.7 | Negative | FALSE | TRUE | 6/11/2024 | 12:32 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bedroom 1 | Door | Casing | Wood | D | |
| 6111213 | 22433 | -0.6 | Negative | FALSE | TRUE | 6/11/2024 | 12:32 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bedroom 1 | Door | Jamb | Wood | D | |
| 6111213 | 22434 | -0.4 | Negative | FALSE | TRUE | 6/11/2024 | 12:33 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bedroom 1 | Room | Baseboard | Wood | D | |
| 6111213 | 22435 | -0.7 | Negative | FALSE | TRUE | 6/11/2024 | 12:33 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bedroom 1 | Window | Casing | Wood | B | |
| 6111213 | 22436 | -0.7 | Negative | FALSE | TRUE | 6/11/2024 | 12:34 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bedroom 1 | Window | Sill | Wood | B | |
| 6111213 | 22437 | 0 | Negative | FALSE | FALSE | 6/11/2024 | 12:35 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bedroom 1 | Room | Wall | Drywall | B | |
| 6111213 | 22438 | -0.1 | Negative | FALSE | FALSE | 6/11/2024 | 12:35 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bedroom 1 | Room | Wall | Drywall | A | |
| 6111213 | 22439 | 0 | Negative | FALSE | FALSE | 6/11/2024 | 12:36 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bedroom 1 | Room | Wall | Drywall | D | |
| 6111213 | 22440 | -0.1 | Negative | FALSE | FALSE | 6/11/2024 | 12:36 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bedroom 1 | Room | Wall | Drywall | C | |
| 6111213 | 22441 | 0 | Negative | FALSE | FALSE | 6/11/2024 | 12:37 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bedroom 1 | Room | Ceiling | Drywall | | |

| Job Id | Reading # | Concentration | Result | Calibration | RTA Present | Date | Time | User | Analytic Mode | Site Address | Area | Unit # | Room | Structure | Member | Substrate | Wall | Location |
|---------|-----------|---------------|----------|-------------|-------------|-----------|----------|-----------------|---------------|--------------|------|--------|---------------------|-----------|---------------|-----------|------|----------|
| 6111213 | 22442 | 0 | Negative | FALSE | FALSE | 6/11/2024 | 12:37 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bedroom 2 | Room | Ceiling | Drywall | | |
| 6111213 | 22443 | 0.1 | Negative | FALSE | FALSE | 6/11/2024 | 12:38 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bedroom 2 | Room | Wall | Drywall | A | |
| 6111213 | 22444 | -0.6 | Negative | FALSE | TRUE | 6/11/2024 | 12:38 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bedroom 2 | Room | Wall | Drywall | B | |
| 6111213 | 22445 | -0.1 | Negative | FALSE | FALSE | 6/11/2024 | 12:39 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bedroom 2 | Room | Wall | Drywall | D | |
| 6111213 | 22446 | 0.1 | Negative | FALSE | FALSE | 6/11/2024 | 12:39 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bedroom 2 | Room | Wall | Drywall | C | |
| 6111213 | 22447 | -0.7 | Negative | FALSE | TRUE | 6/11/2024 | 12:40 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bedroom 2 | Window | Sill | Wood | C | |
| 6111213 | 22448 | -0.6 | Negative | FALSE | TRUE | 6/11/2024 | 12:40 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bedroom 2 | Window | Casing | Wood | C | |
| 6111213 | 22449 | -0.6 | Negative | FALSE | TRUE | 6/11/2024 | 12:41 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bedroom 2 | Closet | Slide Door | Wood | B | |
| 6111213 | 22450 | -0.7 | Negative | FALSE | TRUE | 6/11/2024 | 12:41 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bedroom 2 | Closet | Door Casing | Wood | B | |
| 6111213 | 22451 | -0.4 | Negative | FALSE | TRUE | 6/11/2024 | 12:42 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bedroom 2 | Room | Baseboard | Wood | B | |
| 6111213 | 22452 | -0.9 | Negative | FALSE | TRUE | 6/11/2024 | 12:42 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bedroom 2 | Door | | Wood | A | |
| 6111213 | 22453 | -0.8 | Negative | FALSE | TRUE | 6/11/2024 | 12:43 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bedroom 2 | Door | Jamb | Wood | A | |
| 6111213 | 22454 | -0.8 | Negative | FALSE | TRUE | 6/11/2024 | 12:43 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bedroom 2 | Door | Casing | Wood | A | |
| 6111213 | 22455 | -0.7 | Negative | FALSE | TRUE | 6/11/2024 | 12:44 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bedroom 3 | Door | Casing | Wood | A | |
| 6111213 | 22456 | -0.1 | Negative | FALSE | FALSE | 6/11/2024 | 12:45 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bedroom 3 | Door | Jamb | Wood | A | |
| 6111213 | 22457 | -0.5 | Negative | FALSE | TRUE | 6/11/2024 | 12:45 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bedroom 3 | Door | --- | Wood | A | |
| 6111213 | 22458 | -0.7 | Negative | FALSE | TRUE | 6/11/2024 | 12:45 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bedroom 3 | Closet | Slide Door | Wood | A | |
| 6111213 | 22459 | -0.6 | Negative | FALSE | TRUE | 6/11/2024 | 12:46 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bedroom 3 | Closet | Door Casing | Wood | A | |
| 6111213 | 22460 | -0.8 | Negative | FALSE | TRUE | 6/11/2024 | 12:46 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bedroom 3 | Window | Casing | Wood | D | |
| 6111213 | 22461 | -0.7 | Negative | FALSE | TRUE | 6/11/2024 | 12:47 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bedroom 3 | Window | Sill | Wood | D | |
| 6111213 | 22462 | -0.6 | Negative | FALSE | TRUE | 6/11/2024 | 12:47 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bedroom 3 | Room | Baseboard | Wood | A | |
| 6111213 | 22463 | 0 | Negative | FALSE | FALSE | 6/11/2024 | 12:48 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bedroom 3 | Room | Wall | Drywall | B | |
| 6111213 | 22464 | 0 | Negative | FALSE | FALSE | 6/11/2024 | 12:48 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bedroom 3 | Room | Wall | Drywall | C | |
| 6111213 | 22465 | 0 | Negative | FALSE | FALSE | 6/11/2024 | 12:49 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bedroom 3 | Room | Wall | Drywall | D | |
| 6111213 | 22466 | 0 | Negative | FALSE | FALSE | 6/11/2024 | 12:50 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bedroom 3 | Room | Wall | Drywall | A | |
| 6111213 | 22467 | 0 | Negative | FALSE | FALSE | 6/11/2024 | 12:50 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bedroom 3 | Room | Ceiling | Drywall | | |
| 6111213 | 22468 | 0 | Negative | FALSE | FALSE | 6/11/2024 | 12:51 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bathroom | Room | Ceiling | Drywall | | |
| 6111213 | 22469 | -0.1 | Negative | FALSE | FALSE | 6/11/2024 | 12:52 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bathroom | Room | Wall | Drywall | C | |
| 6111213 | 22470 | -0.1 | Negative | FALSE | FALSE | 6/11/2024 | 12:53 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bathroom | Room | Wall | Drywall | B | |
| 6111213 | 22471 | -0.1 | Negative | FALSE | FALSE | 6/11/2024 | 12:53 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bathroom | Room | Wall | Drywall | A | |
| 6111213 | 22472 | -0.7 | Negative | FALSE | TRUE | 6/11/2024 | 12:54 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bathroom | Door | | Wood | B | |
| 6111213 | 22473 | -0.8 | Negative | FALSE | TRUE | 6/11/2024 | 12:55 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bathroom | Door | Casing | Wood | B | |
| 6111213 | 22474 | -0.7 | Negative | FALSE | TRUE | 6/11/2024 | 12:55 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Bathroom | Door | Jamb | Wood | B | |
| 6111213 | 22475 | -0.8 | Negative | FALSE | TRUE | 6/11/2024 | 12:57 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Basement room 1 | Stair | Door | Wood | D | |
| 6111213 | 22476 | -0.8 | Negative | FALSE | TRUE | 6/11/2024 | 12:58 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Basement room 1 | Stair | Door Casing | Wood | D | |
| 6111213 | 22477 | -0.9 | Negative | FALSE | TRUE | 6/11/2024 | 12:59 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Basement room 1 | Stair | Door Jamb | Wood | D | |
| 6111213 | 22478 | -0.4 | Negative | FALSE | TRUE | 6/11/2024 | 12:59 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Basement room 1 | Stair | Stringer | Wood | | |
| 6111213 | 22479 | -0.8 | Negative | FALSE | TRUE | 6/11/2024 | 1:00 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Basement room 1 | Stair | Newel Post | Wood | | |
| 6111213 | 22480 | -0.9 | Negative | FALSE | TRUE | 6/11/2024 | 1:00 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Basement room 1 | Room | Wall | Wood | D | |
| 6111213 | 22481 | -0.8 | Negative | FALSE | TRUE | 6/11/2024 | 1:01 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Basement room 1 | Room | Wall | Wood | A | |
| 6111213 | 22482 | -0.6 | Negative | FALSE | TRUE | 6/11/2024 | 1:01 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Basement room 1 | Room | Wall | Wood | B | |
| 6111213 | 22483 | -0.7 | Negative | FALSE | TRUE | 6/11/2024 | 1:01 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Basement room 1 | Room | Wall | Wood | C | |
| 6111213 | 22484 | 0 | Negative | FALSE | FALSE | 6/11/2024 | 1:02 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Basement room 1 | Room | Ceiling | Tile | | |
| 6111213 | 22485 | -0.2 | Negative | FALSE | TRUE | 6/11/2024 | 1:02 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Basement room 1 | Room | Crown Molding | Wood | | |
| 6111213 | 22486 | -0.5 | Negative | FALSE | TRUE | 6/11/2024 | 1:03 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Basement room 1 | Window | Casing | Wood | B | |
| 6111213 | 22487 | -0.5 | Negative | FALSE | TRUE | 6/11/2024 | 1:04 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Basement room 1 | Room | Baseboard | Wood | C | |
| 6111213 | 22488 | -0.8 | Negative | FALSE | TRUE | 6/11/2024 | 1:06 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Basement room 1 | Closet | Slide Door | Wood | C | |
| 6111213 | 22489 | -0.5 | Negative | FALSE | TRUE | 6/11/2024 | 1:10 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Basement room 1 | Closet | Door Casing | Wood | C | |
| 6111213 | 22490 | 0.3 | Negative | FALSE | FALSE | 6/11/2024 | 1:10 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Basement room 1 | Closet | Wall | Concrete | C | |
| 6111213 | 22491 | 0 | Negative | FALSE | FALSE | 6/11/2024 | 1:11 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Basement room 1 | Door | | Metal | C | |
| 6111213 | 22492 | 0.4 | Negative | FALSE | FALSE | 6/11/2024 | 1:12 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Boiler/Laundry Room | Room | Floor | Concrete | | |
| 6111213 | 22493 | -0.5 | Negative | FALSE | TRUE | 6/11/2024 | 1:13 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Boiler/Laundry Room | Window | Casing | Wood | B | |
| 6111213 | 22494 | 0.2 | Negative | FALSE | FALSE | 6/11/2024 | 1:14 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Boiler/Laundry Room | Room | Wall | Concrete | A | |
| 6111213 | 22495 | 0.1 | Negative | FALSE | FALSE | 6/11/2024 | 1:14 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Boiler/Laundry Room | Room | Chimney | Concrete | | Lower |
| 6111213 | 22496 | 0.1 | Negative | FALSE | FALSE | 6/11/2024 | 1:15 PM | Danny Feliciano | Paint | 4 Brook Rd | Unit | | Boiler/Laundry Room | Room | Chimney | Concrete | | Upper |

Company LEW Corporation
XRF Make Heuresis
Model Pb200i
Serial Num. 2128
Lead concentration units: mg/cm2
Total Readings: 113 Total Positives 0
Action Level 1
Mode Action Level
Analytic Mode Paint

Actionables

| Job Id | Reading # | Concentration | Result | Calibration | RTA Present | Date | Time | User | Analytic Mode | Site Address | Area | Unit # | Room | Structure | Member | Substrate | Wall | Location |
|----------------|-----------|---------------|--------|-------------|-------------|------|------|------|---------------|--------------|------|--------|------|-----------|--------|-----------|------|----------|
| No Actionables | | | | | | | | | | | | | | | | | | |