

Company LEW Corporation  
 XRF Make Heuresis  
 Model Pb200i  
 Serial Num. 1830  
 Lead concentration units: mg/cm2  
 Total Readings: 75  
 Action Level 1  
 Mode Action Level  
 Analytic Mode Paint

All Readings

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
132 N. Harvard 1	19753	1.2		TRUE	FALSE	6/25/2024	9:58 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ								
132 N. Harvard 1	19754	1.2		TRUE	FALSE	6/25/2024	9:59 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ								
132 N. Harvard 1	19755	1.3		TRUE	FALSE	6/25/2024	10:00 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ								
132 N. Harvard 1	19756	-0.1		TRUE	FALSE	6/25/2024	10:01 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ								
132 N. Harvard 1	19757	-0.1		TRUE	FALSE	6/25/2024	10:02 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ								
132 N. Harvard 1	19758	-0.1		TRUE	FALSE	6/25/2024	10:02 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ								
132 N. Harvard 1	19759	0	Negative	FALSE	FALSE	6/25/2024	10:04 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 1	Window	Sill	Wood	C	1
132 N. Harvard 1	19760	-0.1	Negative	FALSE	FALSE	6/25/2024	10:04 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 1	Window	Casing	Wood	C	1
132 N. Harvard 1	19761	-0.1	Negative	FALSE	FALSE	6/25/2024	10:05 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 1	Window	Jamb	Wood	C	1
132 N. Harvard 1	19762	0.1	Negative	FALSE	FALSE	6/25/2024	10:06 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 1	Closet	Slide Door	Wood	B	1
132 N. Harvard 1	19763	0.1	Negative	FALSE	FALSE	6/25/2024	10:08 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 1	Closet	Shelf Support	Wood	B	1
132 N. Harvard 1	19764	0	Negative	FALSE	FALSE	6/25/2024	10:09 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 1	Closet	Wall	Drywall	B	1
132 N. Harvard 1	19765	-0.1	Negative	FALSE	FALSE	6/25/2024	10:10 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 1	Door	---	Drywall	B	1
132 N. Harvard 1	19766	0	Negative	FALSE	FALSE	6/25/2024	10:10 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 1	Door	Jamb	Wood	B	1
132 N. Harvard 1	19767	-0.1	Negative	FALSE	FALSE	6/25/2024	10:11 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 1	Door	Casing	Wood	B	1
132 N. Harvard 1	19768	0.3	Negative	FALSE	FALSE	6/25/2024	10:13 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 1	Pipe	Horizontal	Metal	C	1
132 N. Harvard 1	19769	0	Negative	FALSE	FALSE	6/25/2024	10:14 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 1	Room	Wall	Brick	C	1
132 N. Harvard 1	19770	0	Negative	FALSE	FALSE	6/25/2024	10:16 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 1	Room	Wall	Drywall	B	1
132 N. Harvard 1	19771	0.1	Negative	FALSE	FALSE	6/25/2024	10:17 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 1	Room	Wall	Drywall	A	1
132 N. Harvard 1	19772	0	Negative	FALSE	FALSE	6/25/2024	10:17 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 1	Room	Wall	Drywall	D	1
132 N. Harvard 1	19773	0.2	Negative	FALSE	FALSE	6/25/2024	10:19 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 3	Door	---	Wood	C	1
132 N. Harvard 1	19774	0	Negative	FALSE	FALSE	6/25/2024	10:20 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 3	Door	Jamb	Wood	C	1
132 N. Harvard 1	19775	0	Negative	FALSE	FALSE	6/25/2024	10:21 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 3	Door	Casing	Wood	C	1
132 N. Harvard 1	19776	0	Negative	FALSE	FALSE	6/25/2024	10:22 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 3	Closet	Slide Door	Wood	C	1
132 N. Harvard 1	19777	-0.1	Negative	FALSE	FALSE	6/25/2024	10:23 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 3	Closet	Shelf Support	Wood	C	1
132 N. Harvard 1	19778	0.1	Negative	FALSE	FALSE	6/25/2024	10:24 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 3	Closet	Wall	Drywall	C	1
132 N. Harvard 1	19779	0.2	Negative	FALSE	FALSE	6/25/2024	10:26 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 3	Window	Sill	Wood	D	1
132 N. Harvard 1	19780	0.1	Negative	FALSE	FALSE	6/25/2024	10:27 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 3	Window	Jamb	Wood	D	1
132 N. Harvard 1	19781	-0.2	Negative	FALSE	FALSE	6/25/2024	10:28 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 3	Window	Casing	Wood	D	1
132 N. Harvard 1	19782	0.4	Negative	FALSE	FALSE	6/25/2024	10:31 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 3	Radiator	---	Metal	D	1
132 N. Harvard 1	19783	0.1	Negative	FALSE	FALSE	6/25/2024	10:32 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 3	Room	Wall	Drywall	D	1
132 N. Harvard 1	19784	0	Negative	FALSE	FALSE	6/25/2024	10:32 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 3	Room	Wall	Drywall	C	1
132 N. Harvard 1	19785	-0.1	Negative	FALSE	FALSE	6/25/2024	10:33 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 3	Room	Wall	Drywall	A	1
132 N. Harvard 1	19786	0	Negative	FALSE	FALSE	6/25/2024	10:34 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 3	Room	Wall	Drywall	B	1
132 N. Harvard 1	19787	0.1	Negative	FALSE	FALSE	6/25/2024	10:35 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 3	Room	Ceiling	Drywall	---	1
132 N. Harvard 1	19788	-0.2	Negative	FALSE	FALSE	6/25/2024	10:36 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 3	Room	Baseboard	Wood	C	1
132 N. Harvard 1	19789	-0.1	Negative	FALSE	FALSE	6/25/2024	10:38 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bathroom 1	Door	Jamb	Wood	B	1
132 N. Harvard 1	19790	0	Negative	FALSE	FALSE	6/25/2024	10:39 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bathroom 1	Door	Casing	Wood	B	1
132 N. Harvard 1	19791	0.1	Negative	FALSE	FALSE	6/25/2024	10:39 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bathroom 1	Door	---	Wood	B	1
132 N. Harvard 1	19792	0	Negative	FALSE	FALSE	6/25/2024	10:40 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bathroom 1	Window	Sill	Wood	D	1
132 N. Harvard 1	19793	-0.2	Negative	FALSE	FALSE	6/25/2024	10:42 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bathroom 1	Window	Casing	Wood	D	1
132 N. Harvard 1	19794	0	Negative	FALSE	FALSE	6/25/2024	10:42 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bathroom 1	Window	Jamb	Wood	D	1
132 N. Harvard 1	19795	0.1	Negative	FALSE	FALSE	6/25/2024	10:44 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bathroom 1	Radiator	---	Metal	D	1
132 N. Harvard 1	19796	0.1	Negative	FALSE	FALSE	6/25/2024	10:46 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bathroom 1	Pipe	Horizontal	Drywall	D	1
132 N. Harvard 1	19797	0.1	Negative	FALSE	FALSE	6/25/2024	10:47 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bathroom 1	Room	Ceiling	Drywall	---	1
132 N. Harvard 1	19798	-0.2	Negative	FALSE	FALSE	6/25/2024	10:48 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bathroom 1	Room	Wall	Drywall	A	1
132 N. Harvard 1	19799	0	Negative	FALSE	FALSE	6/25/2024	10:49 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bathroom 1	Room	Wall	Drywall	B	1
132 N. Harvard 1	19800	0.2	Negative	FALSE	FALSE	6/25/2024	10:50 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bathroom 1	Room	Wall	Drywall	D	1
132 N. Harvard 1	19801	0	Negative	FALSE	FALSE	6/25/2024	10:52 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bathroom 1	Room	Baseboard	Wood	B	1
132 N. Harvard 1	19802	0.1	Negative	FALSE	FALSE	6/25/2024	10:53 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 2	Door	---	Wood	A	1
132 N. Harvard 1	19803	0.1	Negative	FALSE	FALSE	6/25/2024	10:54 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 2	Door	Jamb	Wood	A	1

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
132 N. Harvard 1	19804	-0.1	Negative	FALSE	FALSE	6/25/2024	10:55 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 2	Door	Casing	Wood	A	1
132 N. Harvard 1	19805	0.1	Negative	FALSE	FALSE	6/25/2024	10:56 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 2	Closet	Slide Door	Wood	C	1
132 N. Harvard 1	19806	0	Negative	FALSE	FALSE	6/25/2024	10:58 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 2	Closet	Shelf Support	Wood	C	1
132 N. Harvard 1	19807	0.2	Negative	FALSE	FALSE	6/25/2024	10:59 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 2	Closet	Wall	Drywall	C	1
132 N. Harvard 1	19808	0.3	Negative	FALSE	FALSE	6/25/2024	11:00 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 2	Window	Sill	Drywall	D	1
132 N. Harvard 1	19809	-0.2	Negative	FALSE	FALSE	6/25/2024	11:01 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 2	Window	Casing	Drywall	D	1
132 N. Harvard 1	19810	0	Negative	FALSE	FALSE	6/25/2024	11:06 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 2	Window	Jamb	Wood	D	1
132 N. Harvard 1	19811	-0.1	Negative	FALSE	FALSE	6/25/2024	11:07 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 2	Room	Ceiling	Drywall		1
132 N. Harvard 1	19812	0.1	Negative	FALSE	FALSE	6/25/2024	11:07 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 2	Room	Wall	Drywall	A	1
132 N. Harvard 1	19813	0.1	Negative	FALSE	FALSE	6/25/2024	11:08 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 2	Room	Wall	Drywall	B	1
132 N. Harvard 1	19814	0	Negative	FALSE	FALSE	6/25/2024	11:08 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 2	Room	Wall	Drywall	C	1
132 N. Harvard 1	19815	0	Negative	FALSE	FALSE	6/25/2024	11:09 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 2	Room	Wall	Drywall	D	1
132 N. Harvard 1	19816	0	Negative	FALSE	FALSE	6/25/2024	11:10 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Bedroom 2	Room	Baseboard	Wood	A	1
132 N. Harvard 1	19817	0	Negative	FALSE	FALSE	6/25/2024	11:12 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Foyer	Room	Baseboard	Wood	D	1
132 N. Harvard 1	19818	-0.1	Negative	FALSE	FALSE	6/25/2024	11:13 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Foyer	Room	Ceiling	Drywall		1
132 N. Harvard 1	19819	0	Negative	FALSE	FALSE	6/25/2024	11:14 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Foyer	Room	Wall	Drywall	C	1
132 N. Harvard 1	19820	0	Negative	FALSE	FALSE	6/25/2024	11:14 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Foyer	Room	Wall	Drywall	B	1
132 N. Harvard 1	19821	-0.4	Negative	FALSE	FALSE	6/25/2024	11:15 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Foyer	Room	Wall	Drywall	A	1
132 N. Harvard 1	19822	0	Negative	FALSE	FALSE	6/25/2024	11:16 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Foyer	Window	Sill	Wood	A	1
132 N. Harvard 1	19823	-0.2	Negative	FALSE	FALSE	6/25/2024	11:17 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Foyer	Window	Casing	Wood	A	1
132 N. Harvard 1	19824	0	Negative	FALSE	FALSE	6/25/2024	11:18 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Foyer	Window	Jamb	Wood	A	1
132 N. Harvard 1	19825	0.7	Negative	FALSE	FALSE	6/25/2024	11:19 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Living Room/Kitchen	Window	Sill	Wood	B	1
132 N. Harvard 1	19826	-0.2	Negative	FALSE	FALSE	6/25/2024	11:21 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Living Room/Kitchen	Window	Casing	Wood	B	1
132 N. Harvard 1	19827	-0.1	Negative	FALSE	FALSE	6/25/2024	11:21 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Living Room/Kitchen	Window	Jamb	Wood	B	1
132 N. Harvard 1	19828	0	Negative	FALSE	FALSE	6/25/2024	11:22 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Living Room/Kitchen	Room	Baseboard	Wood	B	1
132 N. Harvard 1	19829	0	Negative	FALSE	FALSE	6/25/2024	11:23 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Living Room/Kitchen	Room	Ceiling	Drywall		1
132 N. Harvard 1	19830	0	Negative	FALSE	FALSE	6/25/2024	11:24 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Living Room/Kitchen	Room	Wall	Drywall	A	1
132 N. Harvard 1	19831	0.1	Negative	FALSE	FALSE	6/25/2024	11:24 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Living Room/Kitchen	Room	Wall	Drywall	B	1
132 N. Harvard 1	19832	0.1	Negative	FALSE	FALSE	6/25/2024	11:25 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Living Room/Kitchen	Room	Wall	Drywall	C	1
132 N. Harvard 1	19833	0.1	Negative	FALSE	FALSE	6/25/2024	11:26 AM	Nyire Edmonds-Grant	Paint	132 N. Harvard Ave, Ventnor City, NJ	Unit		Living Room/Kitchen	Room	Wall	Drywall	D	1

Company LEW Corporation  
XRF Make Heuresis  
Model Pb200i  
Serial Num. 1830

Lead concentration units: mg/cm2

Total Readings: 75 Total Positives 0  
Action Level 1  
Mode Action Level  
Analytic Mode Paint

### Actionables

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
No Actionables																		