

Company LEW Corporation
 XRF Make Heuresis
 Model Pb200i
 Serial Num. 1830

Lead concentration units: mg/cm2
 Total Readings: 72
 Action Level 1
 Mode Action Level
 Analytic Mode Paint

All Readings

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
132 N. Ventnor 2	19834	1.2		TRUE	FALSE	6/27/2024	2:33 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ								
132 N. Ventnor 2	19835	1.2		TRUE	FALSE	6/27/2024	2:34 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ								
132 N. Ventnor 2	19836	1.2		TRUE	FALSE	6/27/2024	2:35 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ								
132 N. Ventnor 2	19837	0		TRUE	FALSE	6/27/2024	2:36 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ								
132 N. Ventnor 2	19838	0		TRUE	FALSE	6/27/2024	2:37 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ								
132 N. Ventnor 2	19839	0		TRUE	FALSE	6/27/2024	2:37 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ								
132 N. Ventnor 2	19840	-0.1	Negative	FALSE	FALSE	6/27/2024	2:38 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bathroom	Room	Wall	Drywall	C	1
132 N. Ventnor 2	19841	0	Negative	FALSE	FALSE	6/27/2024	2:39 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bathroom	Room	Wall	Drywall	B	1
132 N. Ventnor 2	19842	0.1	Negative	FALSE	FALSE	6/27/2024	2:40 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bathroom	Room	Wall	Drywall	A	1
132 N. Ventnor 2	19843	0.1	Negative	FALSE	FALSE	6/27/2024	2:41 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bathroom	Room	Wall	Drywall	D	1
132 N. Ventnor 2	19844	0	Negative	FALSE	FALSE	6/27/2024	2:41 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bathroom	Room	Ceiling	Drywall		1
132 N. Ventnor 2	19845	0	Negative	FALSE	FALSE	6/27/2024	2:43 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bathroom	Room	Baseboard	Wood	B	1
132 N. Ventnor 2	19846	0.1	Negative	FALSE	FALSE	6/27/2024	2:43 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bathroom	Door	---	Wood	B	1
132 N. Ventnor 2	19847	0	Negative	FALSE	FALSE	6/27/2024	2:44 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bathroom	Door	Casing	Wood	B	1
132 N. Ventnor 2	19848	-0.3	Negative	FALSE	FALSE	6/27/2024	2:45 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bathroom	Door	Jamb	Wood	B	1
132 N. Ventnor 2	19849	0.1	Negative	FALSE	FALSE	6/27/2024	2:46 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bathroom	Window	Casing	Wood	D	1
132 N. Ventnor 2	19850	0.2	Negative	FALSE	FALSE	6/27/2024	2:47 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bathroom	Radiator		Metal	D	1
132 N. Ventnor 2	19851	0.1	Negative	FALSE	FALSE	6/27/2024	2:48 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bedroom 3	Radiator		Metal	D	1
132 N. Ventnor 2	19852	0.1	Negative	FALSE	FALSE	6/27/2024	2:48 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bedroom 3	Door	---	Wood	C	1
132 N. Ventnor 2	19853	0.1	Negative	FALSE	FALSE	6/27/2024	2:49 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bedroom 3	Door	Casing	Wood	C	1
132 N. Ventnor 2	19854	0.1	Negative	FALSE	FALSE	6/27/2024	2:50 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bedroom 3	Door	Jamb	Wood	C	1
132 N. Ventnor 2	19855	-0.1	Negative	FALSE	FALSE	6/27/2024	2:51 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bedroom 3	Closet	Slide Door	Wood	C	1
132 N. Ventnor 2	19856	0	Negative	FALSE	FALSE	6/27/2024	2:51 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bedroom 3	Closet	Door Casing	Wood	C	1
132 N. Ventnor 2	19857	0	Negative	FALSE	FALSE	6/27/2024	2:52 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bedroom 3	Closet	Door Jamb	Wood	C	1
132 N. Ventnor 2	19858	0.1	Negative	FALSE	FALSE	6/27/2024	2:53 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bedroom 3	Window	Casing	Wood	A	1
132 N. Ventnor 2	19859	0.1	Negative	FALSE	FALSE	6/27/2024	2:54 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bedroom 3	Room	Wall	Drywall	A	1
132 N. Ventnor 2	19860	0	Negative	FALSE	FALSE	6/27/2024	2:54 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bedroom 3	Room	Wall	Drywall	B	1
132 N. Ventnor 2	19861	0	Negative	FALSE	FALSE	6/27/2024	2:55 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bedroom 3	Room	Wall	Drywall	C	1
132 N. Ventnor 2	19862	0	Negative	FALSE	FALSE	6/27/2024	2:56 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bedroom 3	Room	Wall	Drywall	D	1
132 N. Ventnor 2	19863	0	Negative	FALSE	FALSE	6/27/2024	2:56 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bedroom 3	Room	Ceiling	Drywall		1
132 N. Ventnor 2	19864	-0.1	Negative	FALSE	FALSE	6/27/2024	2:57 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bedroom 3	Room	Baseboard	Wood	B	1
132 N. Ventnor 2	19865	0.1	Negative	FALSE	FALSE	6/27/2024	2:58 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bedroom 2	Door		Wood	A	1
132 N. Ventnor 2	19866	0	Negative	FALSE	FALSE	6/27/2024	2:59 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bedroom 2	Door	Casing	Wood	A	1
132 N. Ventnor 2	19867	-0.2	Negative	FALSE	FALSE	6/27/2024	3:00 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bedroom 2	Door	Jamb	Wood	A	1
132 N. Ventnor 2	19868	0	Negative	FALSE	FALSE	6/27/2024	3:00 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bedroom 2	Window	Casing	Wood	D	1
132 N. Ventnor 2	19869	0	Negative	FALSE	FALSE	6/27/2024	3:01 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bedroom 2	Closet	Slide Door	Wood	C	1
132 N. Ventnor 2	19870	0.1	Negative	FALSE	FALSE	6/27/2024	3:02 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bedroom 2	Closet	Door Casing	Wood	C	1
132 N. Ventnor 2	19871	0.1	Negative	FALSE	FALSE	6/27/2024	3:03 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bedroom 2	Closet	Door Jamb	Wood	C	1
132 N. Ventnor 2	19872	0	Negative	FALSE	FALSE	6/27/2024	3:04 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bedroom 2	Radiator		Metal	C	1
132 N. Ventnor 2	19873	0.1	Negative	FALSE	FALSE	6/27/2024	3:05 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bedroom 2	Room	Baseboard	Wood	A	1
132 N. Ventnor 2	19874	0	Negative	FALSE	FALSE	6/27/2024	3:05 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bedroom 2	Room	Wall	Drywall	A	1
132 N. Ventnor 2	19875	0.1	Negative	FALSE	FALSE	6/27/2024	3:06 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bedroom 2	Room	Wall	Drywall	B	1
132 N. Ventnor 2	19876	0.1	Negative	FALSE	FALSE	6/27/2024	3:07 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bedroom 2	Room	Wall	Drywall	C	1
132 N. Ventnor 2	19877	0	Negative	FALSE	FALSE	6/27/2024	3:07 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bedroom 2	Room	Wall	Drywall	D	1
132 N. Ventnor 2	19878	-0.1	Negative	FALSE	FALSE	6/27/2024	3:08 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bedroom 1	Door	Jamb	Wood	B	1
132 N. Ventnor 2	19879	0.1	Negative	FALSE	FALSE	6/27/2024	3:09 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bedroom 1	Door	Casing	Wood	B	1
132 N. Ventnor 2	19880	0.1	Negative	FALSE	FALSE	6/27/2024	3:10 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bedroom 1	Door	---	Wood	B	1
132 N. Ventnor 2	19881	0	Negative	FALSE	FALSE	6/27/2024	3:11 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bedroom 1	Window	Casing	Wood	D	1
132 N. Ventnor 2	19882	0.1	Negative	FALSE	FALSE	6/27/2024	3:12 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bedroom 1	Closet	Door Casing	Wood	B	1
132 N. Ventnor 2	19883	0.1	Negative	FALSE	FALSE	6/27/2024	3:12 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bedroom 1	Closet	Door Jamb	Wood	B	1
132 N. Ventnor 2	19884	0	Negative	FALSE	FALSE	6/27/2024	3:13 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Bedroom 1	Closet	Slide Door	Wood	B	1

Company LEW Corporation
 XRF Make Heuresis
 Model Pb200i
 Serial Num. 1830

Lead concentration units: mg/cm2
 Total Readings: 72 Total Positives 1
 Action Level 1
 Mode Action Level
 Analytic Mode Paint

Actionables

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
132 N. Ventnor 2	19904	1.9	Positive	FALSE	FALSE	6/27/2024	3:31 PM	Nyire Edmonds-Grant	Paint	132 N. Harvard, Ventnor City, NJ	Unit		Foyer	Window	Sash	Wood	D	1