

Company LEW Corporation
 XRF Make Heuresis
 Model Pb200i
 Serial Num. 1834
 Lead concentration units: mg/cm2
 Total Readings: 152
 Action Level 1
 Mode Action Level
 Analytic Mode Paint

All Readings

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
6111259	39806	0.9		TRUE	FALSE	6/11/2024	1:00 PM	Paint	9 Liberty Blvd								
6111259	39807	0.9		TRUE	FALSE	6/11/2024	1:00 PM	Paint	9 Liberty Blvd								
6111259	39808	1		TRUE	FALSE	6/11/2024	1:01 PM	Paint	9 Liberty Blvd								
6111259	39809	0		TRUE	FALSE	6/11/2024	1:02 PM	Paint	9 Liberty Blvd								
6111259	39810	-0.1		TRUE	FALSE	6/11/2024	1:02 PM	Paint	9 Liberty Blvd								
6111259	39811	-0.1		TRUE	FALSE	6/11/2024	1:02 PM	Paint	9 Liberty Blvd								
6111259	39812	-0.2	Negative	FALSE	FALSE	6/11/2024	1:03 PM	Paint	9 Liberty Blvd	Unit		Living Room	Door	---	Wood	A	1
6111259	39813	-0.2	Negative	FALSE	FALSE	6/11/2024	1:03 PM	Paint	9 Liberty Blvd	Unit		Living Room	Door	Casing	Wood	A	1
6111259	39814	-0.1	Negative	FALSE	FALSE	6/11/2024	1:04 PM	Paint	9 Liberty Blvd	Unit		Living Room	Closet	Door	Wood	C	1
6111259	39815	-0.1	Negative	FALSE	FALSE	6/11/2024	1:04 PM	Paint	9 Liberty Blvd	Unit		Living Room	Closet	Door Casing	Wood	C	1
6111259	39816	-0.2	Negative	FALSE	FALSE	6/11/2024	1:05 PM	Paint	9 Liberty Blvd	Unit		Living Room	Closet	Door Jamb	Wood	C	1
6111259	39817	-0.3	Negative	FALSE	FALSE	6/11/2024	1:05 PM	Paint	9 Liberty Blvd	Unit		Living Room	Closet	Shelf Support	Wood	C	1
6111259	39818	-0.1	Negative	FALSE	FALSE	6/11/2024	1:06 PM	Paint	9 Liberty Blvd	Unit		Living Room	Closet	Shelf	Wood	C	1
6111259	39819	-0.1	Negative	FALSE	FALSE	6/11/2024	1:06 PM	Paint	9 Liberty Blvd	Unit		Living Room	Closet	Floor	Wood	C	1
6111259	39820	-0.1	Negative	FALSE	FALSE	6/11/2024	1:07 PM	Paint	9 Liberty Blvd	Unit		Living Room	Closet	Wall	Drywall	C	1
6111259	39821	0	Negative	FALSE	FALSE	6/11/2024	1:07 PM	Paint	9 Liberty Blvd	Unit		Living Room	Window	Casing	Wood	A	1
6111259	39822	-0.1	Negative	FALSE	FALSE	6/11/2024	1:08 PM	Paint	9 Liberty Blvd	Unit		Living Room	Window	Sill	Wood	A	1
6111259	39823	-0.1	Negative	FALSE	FALSE	6/11/2024	1:08 PM	Paint	9 Liberty Blvd	Unit		Living Room	Window	Apron	Wood	A	1
6111259	39824	0	Negative	FALSE	FALSE	6/11/2024	1:09 PM	Paint	9 Liberty Blvd	Unit		Living Room	Radiator	Baseboard	Metal	A	1
6111259	39825	0	Negative	FALSE	FALSE	6/11/2024	1:09 PM	Paint	9 Liberty Blvd	Unit		Living Room	Room	Floor	Wood	A	1
6111259	39826	0	Negative	FALSE	FALSE	6/11/2024	1:10 PM	Paint	9 Liberty Blvd	Unit		Living Room	Room	Baseboard	Wood	A	1
6111259	39827	0	Negative	FALSE	FALSE	6/11/2024	1:10 PM	Paint	9 Liberty Blvd	Unit		Living Room	Room	Ceiling	Drywall	A	1
6111259	39828	0.1	Negative	FALSE	FALSE	6/11/2024	1:11 PM	Paint	9 Liberty Blvd	Unit		Living Room	Room	Wall	Drywall	A	1
6111259	39829	0	Negative	FALSE	FALSE	6/11/2024	1:11 PM	Paint	9 Liberty Blvd	Unit		Living Room	Room	Wall	Drywall	B	1
6111259	39830	0.1	Negative	FALSE	FALSE	6/11/2024	1:12 PM	Paint	9 Liberty Blvd	Unit		Living Room	Room	Wall	Drywall	C	1
6111259	39831	0	Negative	FALSE	FALSE	6/11/2024	1:12 PM	Paint	9 Liberty Blvd	Unit		Living Room	Room	Wall	Drywall	D	1
6111259	39832	0	Negative	FALSE	FALSE	6/11/2024	1:13 PM	Paint	9 Liberty Blvd	Unit		Dining Room	Room	Wall	Drywall	A	1
6111259	39833	0.1	Negative	FALSE	FALSE	6/11/2024	1:13 PM	Paint	9 Liberty Blvd	Unit		Dining Room	Room	Wall	Drywall	B	1
6111259	39834	0.1	Negative	FALSE	FALSE	6/11/2024	1:14 PM	Paint	9 Liberty Blvd	Unit		Dining Room	Room	Wall	Drywall	C	1
6111259	39835	0.1	Negative	FALSE	FALSE	6/11/2024	1:14 PM	Paint	9 Liberty Blvd	Unit		Dining Room	Room	Wall	Drywall	D	1
6111259	39836	0.1	Negative	FALSE	FALSE	6/11/2024	1:15 PM	Paint	9 Liberty Blvd	Unit		Dining Room	Room	Ceiling	Drywall	D	1
6111259	39837	-0.1	Negative	FALSE	FALSE	6/11/2024	1:15 PM	Paint	9 Liberty Blvd	Unit		Dining Room	Room	Baseboard	Wood	B	1
6111259	39838	-0.1	Negative	FALSE	FALSE	6/11/2024	1:16 PM	Paint	9 Liberty Blvd	Unit		Dining Room	Room	Floor	Wood	B	1
6111259	39839	-0.1	Negative	FALSE	FALSE	6/11/2024	1:17 PM	Paint	9 Liberty Blvd	Unit		Dining Room	Radiator	Baseboard	Metal	C	1
6111259	39840	-0.1	Negative	FALSE	FALSE	6/11/2024	1:18 PM	Paint	9 Liberty Blvd	Unit		Dining Room	Window	Casing	Wood	C	1
6111259	39841	-0.2	Negative	FALSE	FALSE	6/11/2024	1:18 PM	Paint	9 Liberty Blvd	Unit		Dining Room	Window	Sill	Wood	C	1
6111259	39842	-0.1	Negative	FALSE	FALSE	6/11/2024	1:19 PM	Paint	9 Liberty Blvd	Unit		Dining Room	Window	Apron	Wood	C	1
6111259	39843	0	Negative	FALSE	FALSE	6/11/2024	1:20 PM	Paint	9 Liberty Blvd	Unit		Dining Room	Door	---	Wood	A	1
6111259	39844	-0.2	Negative	FALSE	FALSE	6/11/2024	1:20 PM	Paint	9 Liberty Blvd	Unit		Dining Room	Door	Jamb	Wood	A	1

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
6111259	39845	0	Negative	FALSE	FALSE	6/11/2024	1:20 PM	Paint	9 Liberty Blvd	Unit		Dining Room	Door	Casing	Wood	A	1
6111259	39846	0	Negative	FALSE	FALSE	6/11/2024	1:21 PM	Paint	9 Liberty Blvd	Unit		Kitchen	Room	Baseboard	Wood	A	1
6111259	39847	0.1	Negative	FALSE	FALSE	6/11/2024	1:22 PM	Paint	9 Liberty Blvd	Unit		Kitchen	Room	Ceiling	Drywall	A	1
6111259	39848	0	Negative	FALSE	FALSE	6/11/2024	1:22 PM	Paint	9 Liberty Blvd	Unit		Kitchen	Room	Wall	Drywall	A	1
6111259	39849	0.2	Negative	FALSE	FALSE	6/11/2024	1:23 PM	Paint	9 Liberty Blvd	Unit		Kitchen	Room	Wall	Drywall	B	1
6111259	39850	0	Negative	FALSE	FALSE	6/11/2024	1:23 PM	Paint	9 Liberty Blvd	Unit		Kitchen	Room	Wall	Drywall	C	1
6111259	39851	0	Negative	FALSE	FALSE	6/11/2024	1:24 PM	Paint	9 Liberty Blvd	Unit		Kitchen	Room	Wall	Drywall	D	1
6111259	39852	0.1	Negative	FALSE	FALSE	6/11/2024	1:24 PM	Paint	9 Liberty Blvd	Unit		Kitchen	Cabinets	Door	Wood	D	1
6111259	39853	-0.1	Negative	FALSE	FALSE	6/11/2024	1:25 PM	Paint	9 Liberty Blvd	Unit		Kitchen	Cabinets	Frame	Wood	D	1
6111259	39854	0	Negative	FALSE	FALSE	6/11/2024	1:25 PM	Paint	9 Liberty Blvd	Unit		Kitchen	Window	Casing	Wood	C	1
6111259	39855	-0.2	Negative	FALSE	FALSE	6/11/2024	1:26 PM	Paint	9 Liberty Blvd	Unit		Kitchen	Window	Sill	Wood	C	1
6111259	39856	0.1	Negative	FALSE	FALSE	6/11/2024	1:26 PM	Paint	9 Liberty Blvd	Unit		Kitchen	Door	---	Wood	B	1
6111259	39857	0	Negative	FALSE	FALSE	6/11/2024	1:27 PM	Paint	9 Liberty Blvd	Unit		Kitchen	Door	Casing	Wood	B	1
6111259	39858	0	Negative	FALSE	FALSE	6/11/2024	1:27 PM	Paint	9 Liberty Blvd	Unit		Kitchen	Radiator	Baseboard	Metal	B	1
6111259	39859	0	Negative	FALSE	FALSE	6/11/2024	1:28 PM	Paint	9 Liberty Blvd	Unit		Bathroom	Radiator	Baseboard	Metal	C	1
6111259	39860	-0.1	Negative	FALSE	FALSE	6/11/2024	1:29 PM	Paint	9 Liberty Blvd	Unit		Bathroom	Window	Casing	Wood	C	1
6111259	39861	-0.3	Negative	FALSE	FALSE	6/11/2024	1:29 PM	Paint	9 Liberty Blvd	Unit		Bathroom	Window	Sill	Wood	C	1
6111259	39862	-0.1	Negative	FALSE	FALSE	6/11/2024	1:30 PM	Paint	9 Liberty Blvd	Unit		Bathroom	Window	Apron	Wood	C	1
6111259	39863	-0.1	Negative	FALSE	FALSE	6/11/2024	1:30 PM	Paint	9 Liberty Blvd	Unit		Bathroom	Cabinets	Door	Wood	D	1
6111259	39864	0	Negative	FALSE	FALSE	6/11/2024	1:31 PM	Paint	9 Liberty Blvd	Unit		Bathroom	Cabinets	Frame	Wood	D	1
6111259	39865	0	Negative	FALSE	FALSE	6/11/2024	1:31 PM	Paint	9 Liberty Blvd	Unit		Bathroom	Closet	Door	Wood	B	1
6111259	39866	-0.2	Negative	FALSE	FALSE	6/11/2024	1:32 PM	Paint	9 Liberty Blvd	Unit		Bathroom	Closet	Door Casing	Wood	B	1
6111259	39867	-0.2	Negative	FALSE	FALSE	6/11/2024	1:32 PM	Paint	9 Liberty Blvd	Unit		Bathroom	Closet	Shelf Support	Wood	B	1
6111259	39868	0	Negative	FALSE	FALSE	6/11/2024	1:33 PM	Paint	9 Liberty Blvd	Unit		Bathroom	Closet	Shelf	Wood	B	1
6111259	39869	0	Negative	FALSE	FALSE	6/11/2024	1:33 PM	Paint	9 Liberty Blvd	Unit		Bathroom	Closet	Wall	Drywall	B	1
6111259	39870	-0.1	Negative	FALSE	FALSE	6/11/2024	1:34 PM	Paint	9 Liberty Blvd	Unit		Bathroom	Door	---	Wood	A	1
6111259	39871	-0.1	Negative	FALSE	FALSE	6/11/2024	1:34 PM	Paint	9 Liberty Blvd	Unit		Bathroom	Door	Jamb	Wood	A	1
6111259	39872	-0.1	Negative	FALSE	FALSE	6/11/2024	1:35 PM	Paint	9 Liberty Blvd	Unit		Bathroom	Door	Casing	Wood	A	1
6111259	39873	-0.2	Negative	FALSE	FALSE	6/11/2024	1:35 PM	Paint	9 Liberty Blvd	Unit		Bathroom	Room	Baseboard	Wood	A	1
6111259	39874	0.1	Negative	FALSE	FALSE	6/11/2024	1:36 PM	Paint	9 Liberty Blvd	Unit		Bathroom	Room	Wall	Drywall	A	1
6111259	39875	0	Negative	FALSE	FALSE	6/11/2024	1:36 PM	Paint	9 Liberty Blvd	Unit		Bathroom	Room	Wall	Drywall	B	1
6111259	39876	-0.1	Negative	FALSE	FALSE	6/11/2024	1:37 PM	Paint	9 Liberty Blvd	Unit		Bathroom	Room	Wall	Drywall	C	1
6111259	39877	0.1	Negative	FALSE	FALSE	6/11/2024	1:37 PM	Paint	9 Liberty Blvd	Unit		Bathroom	Room	Wall	Drywall	D	1
6111259	39878	0.1	Negative	FALSE	FALSE	6/11/2024	1:38 PM	Paint	9 Liberty Blvd	Unit		Bathroom	Room	Ceiling	Drywall	D	1
6111259	39879	0.1	Negative	FALSE	FALSE	6/11/2024	1:39 PM	Paint	9 Liberty Blvd	Unit		1/2 Bathroom	Room	Ceiling	Drywall	A	1
6111259	39880	0	Negative	FALSE	FALSE	6/11/2024	1:40 PM	Paint	9 Liberty Blvd	Unit		1/2 Bathroom	Room	Wall	Drywall	A	1
6111259	39881	0	Negative	FALSE	FALSE	6/11/2024	1:40 PM	Paint	9 Liberty Blvd	Unit		1/2 Bathroom	Room	Wall	Drywall	B	1
6111259	39882	0	Negative	FALSE	FALSE	6/11/2024	1:41 PM	Paint	9 Liberty Blvd	Unit		1/2 Bathroom	Room	Wall	Drywall	C	1
6111259	39883	-0.1	Negative	FALSE	FALSE	6/11/2024	1:41 PM	Paint	9 Liberty Blvd	Unit		1/2 Bathroom	Room	Wall	Drywall	D	1
6111259	39884	0	Negative	FALSE	FALSE	6/11/2024	1:42 PM	Paint	9 Liberty Blvd	Unit		1/2 Bathroom	Room	Ceiling	Drywall	D	1
6111259	39885	0	Negative	FALSE	FALSE	6/11/2024	1:42 PM	Paint	9 Liberty Blvd	Unit		1/2 Bathroom	Cabinets	Door	Wood	B	1
6111259	39886	-0.2	Negative	FALSE	FALSE	6/11/2024	1:43 PM	Paint	9 Liberty Blvd	Unit		1/2 Bathroom	Cabinets	Frame	Wood	B	1
6111259	39887	0	Negative	FALSE	FALSE	6/11/2024	1:43 PM	Paint	9 Liberty Blvd	Unit		1/2 Bathroom	Radiator	Baseboard	Metal	C	1
6111259	39888	-0.1	Negative	FALSE	FALSE	6/11/2024	1:44 PM	Paint	9 Liberty Blvd	Unit		1/2 Bathroom	Window	Casing	Wood	C	1
6111259	39889	-0.2	Negative	FALSE	FALSE	6/11/2024	1:44 PM	Paint	9 Liberty Blvd	Unit		1/2 Bathroom	Window	Sill	Wood	C	1
6111259	39890	-0.1	Negative	FALSE	FALSE	6/11/2024	1:45 PM	Paint	9 Liberty Blvd	Unit		1/2 Bathroom	Window	Apron	Wood	C	1
6111259	39891	0	Negative	FALSE	FALSE	6/11/2024	1:45 PM	Paint	9 Liberty Blvd	Unit		1/2 Bathroom	Door	---	Wood	D	1
6111259	39892	-0.1	Negative	FALSE	FALSE	6/11/2024	1:46 PM	Paint	9 Liberty Blvd	Unit		1/2 Bathroom	Door	Casing	Wood	D	1
6111259	39893	-0.1	Negative	FALSE	FALSE	6/11/2024	1:46 PM	Paint	9 Liberty Blvd	Unit		1/2 Bathroom	Door	Jamb	Wood	D	1

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
6111259	39894	-0.1	Negative	FALSE	FALSE	6/11/2024	1:47 PM	Paint	9 Liberty Blvd	Unit		Bedroom 2	Door	Jamb	Wood	B	1
6111259	39895	-0.1	Negative	FALSE	FALSE	6/11/2024	1:47 PM	Paint	9 Liberty Blvd	Unit		Bedroom 2	Door	Casing	Wood	B	1
6111259	39896	0	Negative	FALSE	FALSE	6/11/2024	1:48 PM	Paint	9 Liberty Blvd	Unit		Bedroom 2	Door	---	Wood	B	1
6111259	39897	-0.1	Negative	FALSE	FALSE	6/11/2024	1:48 PM	Paint	9 Liberty Blvd	Unit		Bedroom 2	Closet	Door	Wood	B	1
6111259	39898	-0.1	Negative	FALSE	FALSE	6/11/2024	1:49 PM	Paint	9 Liberty Blvd	Unit		Bedroom 2	Closet	Door Casing	Wood	B	1
6111259	39899	-0.2	Negative	FALSE	FALSE	6/11/2024	1:49 PM	Paint	9 Liberty Blvd	Unit		Bedroom 2	Closet	Door Jamb	Wood	B	1
6111259	39900	0	Negative	FALSE	FALSE	6/11/2024	1:50 PM	Paint	9 Liberty Blvd	Unit		Bedroom 2	Radiator	Baseboard	Metal	C	1
6111259	39901	0	Negative	FALSE	FALSE	6/11/2024	1:50 PM	Paint	9 Liberty Blvd	Unit		Bedroom 2	Window	Casing	Wood	C	1
6111259	39902	-0.1	Negative	FALSE	FALSE	6/11/2024	1:51 PM	Paint	9 Liberty Blvd	Unit		Bedroom 2	Window	Sill	Wood	C	1
6111259	39903	-0.2	Negative	FALSE	FALSE	6/11/2024	1:51 PM	Paint	9 Liberty Blvd	Unit		Bedroom 2	Window	Apron	Wood	C	1
6111259	39904	0.1	Negative	FALSE	FALSE	6/11/2024	1:52 PM	Paint	9 Liberty Blvd	Unit		Bedroom 2	Room	Floor	Wood	A	1
6111259	39905	-0.2	Negative	FALSE	FALSE	6/11/2024	1:52 PM	Paint	9 Liberty Blvd	Unit		Bedroom 2	Room	Baseboard	Wood	A	1
6111259	39906	0.1	Negative	FALSE	FALSE	6/11/2024	1:53 PM	Paint	9 Liberty Blvd	Unit		Bedroom 2	Room	Wall	Drywall	A	1
6111259	39907	0	Negative	FALSE	FALSE	6/11/2024	1:53 PM	Paint	9 Liberty Blvd	Unit		Bedroom 2	Room	Wall	Drywall	B	1
6111259	39908	0	Negative	FALSE	FALSE	6/11/2024	1:54 PM	Paint	9 Liberty Blvd	Unit		Bedroom 2	Room	Wall	Drywall	C	1
6111259	39909	0	Negative	FALSE	FALSE	6/11/2024	1:54 PM	Paint	9 Liberty Blvd	Unit		Bedroom 2	Room	Wall	Drywall	D	1
6111259	39910	0	Negative	FALSE	FALSE	6/11/2024	1:54 PM	Paint	9 Liberty Blvd	Unit		Bedroom 2	Room	Ceiling	Drywall	D	1
6111259	39911	-0.1	Negative	FALSE	FALSE	6/11/2024	1:55 PM	Paint	9 Liberty Blvd	Unit		Bedroom 1	Room	Ceiling	Drywall	D	1
6111259	39912	0	Negative	FALSE	FALSE	6/11/2024	1:56 PM	Paint	9 Liberty Blvd	Unit		Bedroom 1	Room	Wall	Drywall	D	1
6111259	39913	0.1	Negative	FALSE	FALSE	6/11/2024	1:56 PM	Paint	9 Liberty Blvd	Unit		Bedroom 1	Room	Wall	Drywall	C	1
6111259	39914	0	Negative	FALSE	FALSE	6/11/2024	1:56 PM	Paint	9 Liberty Blvd	Unit		Bedroom 1	Room	Wall	Drywall	B	1
6111259	39915	0	Negative	FALSE	FALSE	6/11/2024	1:57 PM	Paint	9 Liberty Blvd	Unit		Bedroom 1	Room	Wall	Drywall	A	1
6111259	39916	-0.2	Negative	FALSE	FALSE	6/11/2024	1:57 PM	Paint	9 Liberty Blvd	Unit		Bedroom 1	Room	Baseboard	Wood	B	1
6111259	39917	-0.1	Negative	FALSE	FALSE	6/11/2024	1:58 PM	Paint	9 Liberty Blvd	Unit		Bedroom 1	Room	Floor	Wood	B	1
6111259	39918	0	Negative	FALSE	FALSE	6/11/2024	1:58 PM	Paint	9 Liberty Blvd	Unit		Bedroom 1	Radiator	Baseboard	Metal	A	1
6111259	39919	-0.1	Negative	FALSE	FALSE	6/11/2024	1:59 PM	Paint	9 Liberty Blvd	Unit		Bedroom 1	Window	Casing	Wood	A	1
6111259	39920	-0.2	Negative	FALSE	FALSE	6/11/2024	1:59 PM	Paint	9 Liberty Blvd	Unit		Bedroom 1	Window	Sill	Wood	A	1
6111259	39921	-0.1	Negative	FALSE	FALSE	6/11/2024	2:00 PM	Paint	9 Liberty Blvd	Unit		Bedroom 1	Window	Apron	Wood	A	1
6111259	39922	-0.2	Negative	FALSE	FALSE	6/11/2024	2:00 PM	Paint	9 Liberty Blvd	Unit		Bedroom 1	Closet	Door	Wood	D	1
6111259	39923	-0.2	Negative	FALSE	FALSE	6/11/2024	2:01 PM	Paint	9 Liberty Blvd	Unit		Bedroom 1	Closet	Door Casing	Wood	D	1
6111259	39924	-0.2	Negative	FALSE	FALSE	6/11/2024	2:01 PM	Paint	9 Liberty Blvd	Unit		Bedroom 1	Closet	Door Jamb	Wood	D	1
6111259	39925	-0.2	Negative	FALSE	FALSE	6/11/2024	2:02 PM	Paint	9 Liberty Blvd	Unit		Bedroom 1	Closet	Shelf Support	Wood	D	1
6111259	39926	-0.1	Negative	FALSE	FALSE	6/11/2024	2:02 PM	Paint	9 Liberty Blvd	Unit		Bedroom 1	Closet	Shelf	Wood	D	1
6111259	39927	-0.1	Negative	FALSE	FALSE	6/11/2024	2:03 PM	Paint	9 Liberty Blvd	Unit		Bedroom 1	Door	---	Wood	C	1
6111259	39928	-0.2	Negative	FALSE	FALSE	6/11/2024	2:03 PM	Paint	9 Liberty Blvd	Unit		Bedroom 1	Door	Jamb	Wood	C	1
6111259	39929	-0.1	Negative	FALSE	FALSE	6/11/2024	2:04 PM	Paint	9 Liberty Blvd	Unit		Bedroom 1	Door	Casing	Wood	C	1
6111259	39930	-0.1	Negative	FALSE	FALSE	6/11/2024	2:04 PM	Paint	9 Liberty Blvd	Unit		Bedroom 3	Door	Casing	Wood	C	1
6111259	39931	-0.1	Negative	FALSE	FALSE	6/11/2024	2:05 PM	Paint	9 Liberty Blvd	Unit		Bedroom 3	Door	Jamb	Wood	C	1
6111259	39932	-0.2	Negative	FALSE	FALSE	6/11/2024	2:05 PM	Paint	9 Liberty Blvd	Unit		Bedroom 3	Door	---	Wood	C	1
6111259	39933	0	Negative	FALSE	FALSE	6/11/2024	2:06 PM	Paint	9 Liberty Blvd	Unit		Bedroom 3	Closet	Door	Wood	B	1
6111259	39934	-0.1	Negative	FALSE	FALSE	6/11/2024	2:06 PM	Paint	9 Liberty Blvd	Unit		Bedroom 3	Closet	Door Casing	Wood	B	1
6111259	39935	-0.2	Negative	FALSE	FALSE	6/11/2024	2:07 PM	Paint	9 Liberty Blvd	Unit		Bedroom 3	Closet	Door Jamb	Wood	B	1
6111259	39936	-0.3	Negative	FALSE	FALSE	6/11/2024	2:07 PM	Paint	9 Liberty Blvd	Unit		Bedroom 3	Closet	Shelf Support	Wood	B	1
6111259	39937	-0.2	Negative	FALSE	FALSE	6/11/2024	2:08 PM	Paint	9 Liberty Blvd	Unit		Bedroom 3	Closet	Shelf	Wood	B	1
6111259	39938	0	Negative	FALSE	FALSE	6/11/2024	2:08 PM	Paint	9 Liberty Blvd	Unit		Bedroom 3	Radiator	Baseboard	Metal	A	1
6111259	39939	-0.1	Negative	FALSE	FALSE	6/11/2024	2:09 PM	Paint	9 Liberty Blvd	Unit		Bedroom 3	Window	Casing	Wood	A	1
6111259	39940	-0.2	Negative	FALSE	FALSE	6/11/2024	2:09 PM	Paint	9 Liberty Blvd	Unit		Bedroom 3	Window	Sill	Wood	A	1
6111259	39941	-0.1	Negative	FALSE	FALSE	6/11/2024	2:10 PM	Paint	9 Liberty Blvd	Unit		Bedroom 3	Window	Apron	Wood	A	1
6111259	39942	-0.2	Negative	FALSE	FALSE	6/11/2024	2:10 PM	Paint	9 Liberty Blvd	Unit		Bedroom 3	Room	Baseboard	Wood	B	1

Company LEW Corporation
 XRF Make Heuresis
 Model Pb200i
 Serial Num. 1834
 Lead concentration units: mg/cm2
 Total Readings: 152 Total Positives 0
 Action Level 1
 Mode Action Level
 Analytic Mode Paint

Actionables

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
No Actionables																	