



7469 Whitepine Rd
 North Chesterfield, VA 23237
 Telephone: 800.347.4010

Lead Dust Wipe Analysis Report

Report Number: 24-07-04507

Client: LEW Corp
 181 US Hwy 46
 Mine Hill, NJ 07803

Received Date: 07/25/2024
Analyzed Date: 07/29/2024
Reported Date: 07/30/2024

Project/Test Address: 48392; Mackinney; 42 High St 1st Floor; New Brunswick, NJ

Collection Date: 07/22/2024

Client Number:
 201327

Laboratory Results

Fax Number:
 Ext 18 Melissa

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft ²)	Concentration (ug/ft ²)	Narrative ID
24-07-04507-001	1	BED 1 AL	FL	<5.00	1.00	<5.00	
24-07-04507-002	2	LIVING DC	FL	<5.00	1.00	<5.00	
24-07-04507-003	3	KITCHEN CC	FL	<5.00	1.00	<5.00	
24-07-04507-004	4	BED 2 BL	FL	<5.00	1.00	<5.00	
24-07-04507-005	5	SUN RM CR	FL	<5.00	1.00	<5.00	
24-07-04507-006	6	BED 1 AL	SL	277	0.573	483	
24-07-04507-007	7	LIVING BR	SL	6.10	0.292	20.9	
24-07-04507-008	8	KITCHEN DC	SL	<5.00	0.521	<9.60	
24-07-04507-009	9	BED 2 BR	SL	17.6	0.521	33.7	

Environmental Hazards Services, L.L.C

Client Number: 201327

Report Number: 24-07-04507

Project/Test Address: 48392; Mackinney; 42 High St 1st Floor; New Brunswick, NJ

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft ²)	Concentration (ug/ft ²)	Narrative ID
-------------------	----------------------	---------------------	---------	---------------	------------------------------	-------------------------------------	--------------

Method: ASTM E-1979-17/EPA SW846 7000B

Accreditation #:

Reviewed By Authorized Signatory: Melissa Kanode

Melissa Kanode

QA/QC Clerk

The Reporting Limit (RL) is 5.00 ug Total Pb. Dust wipe area and results are calculated based on area measurements determined by the client. All internal quality control requirements associated with this batch were met, unless otherwise noted.

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, etc., was provided by the client. Results reported above in ug/ft² are calculated based on area supplied by the client. If the report does not contain the result for a field blank, it is due to the fact that the client did not include a field blank with their samples. These sample results do not reflect blank correction. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C.

ELLAP Accreditation through AIHA LAP, LLC (100420), NY ELAP #11714.

Legend	ug = microgram	ug/ft ² = micrograms per square foot	Pb = lead
	mL = milliliter	ft ² = square foot	



LEW CORPORATION
 The Environmental Company™
 LEW Corporation P: (800) 783-0567
 F: (908) 654-8069

Lead

Chain-of-Custody

24-07-04507



Due Date:
 07/30/2024
 (Tuesday)
 AE

* All wipes

SI

any

Project Name: Mackinney
 Address: 42 High St 1st Floor
 City, State: New Brunswick NJ
 Project Number: 48392

Sample Type: Dust wipe Paint chip Soil TCLP

Turn Around Time (TAT): Same Day 3 Day 1 Day Weekend 1 Week 2 Weeks

Name: Mark Franz
 Signature: [Signature]

Sample #	Date Collected	Sample Location (Ex: Fl, Kitchen, AC)	Area (inches)	Paint Chip Analysis		
				mg/cm ²	PPM	% wt
1	7/22/24	Floor, Bed 1 AL	12" x 12"			
2		Living, DC	X			
3		Kitchen, CC	X			
4		Bed 2, BL	X			
5		Sun Rm, CR	X			
6		Sill, Bed 1, AL	2 3/4" x 30"			
7		Living, BR	1 1/2" x 28"			
8		Kitchen, DC	3" x 25"			
9		Bed 2, BR	2 1/2" x 30"			
			X			
			X			
			X			

Relinquished by: Mark Franz Signature: [Signature] Date/Time: 7/22/24 5pm

Received by: [Signature] Signature: [Signature] Date/Time: 7/25/24 3:40 pm