



7469 Whitepine Rd
 North Chesterfield, VA 23237
 Telephone: 800.347.4010

Lead Dust Wipe Analysis Report

Report Number: 24-06-04298

Client: LEW Corp
 181 US Hwy 46
 Mine Hill, NJ 07803

Received Date: 06/27/2024
Analyzed Date: 07/02/2024
Reported Date: 07/02/2024

Project/Test Address: 48977; Violeta Ponce; 96 West Clinton Street; Dover Town, NJ

Collection Date: 06/25/2024

Client Number:
 201327

Laboratory Results

Fax Number:
 Ext 18 Melissa

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft ²)	Concentration (ug/ft ²)	Narrative ID
24-06-04298-001	96-2-1	LR CC	FL	<5.00	1.00	<5.00	
24-06-04298-002	96-2-2	K CC	FL	<5.00	1.00	<5.00	
24-06-04298-003	96-2-3	BR 1 CC	FL	<5.00	1.00	<5.00	
24-06-04298-004	96-2-4	BR 2 CC	FL	<5.00	1.00	<5.00	
24-06-04298-005	96-2-5	S CC	FL	<5.00	1.00	<5.00	
24-06-04298-006	96-2-6	LR A	SL	<5.00	0.630	<7.94	
24-06-04298-007	96-2-7	K B	SL	<5.00	0.917	<5.46	
24-06-04298-008	96-2-8	BR 1 D2	SL	<5.00	0.722	<6.93	
24-06-04298-009	96-2-9	BR 2 A2	SL	9.52	1.81	5.26	

Environmental Hazards Services, L.L.C

Client Number: 201327

Report Number: 24-06-04298

Project/Test Address: 48977; Violeta Ponce; 96 West Clinton Street; Dover
Town, NJ

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft ²)	Concentration (ug/ft ²)	Narrative ID
-------------------	----------------------	---------------------	---------	---------------	------------------------------	-------------------------------------	--------------

Method: ASTM E-1979-17/EPA SW846 7000B

Accreditation #:

Reviewed By Authorized Signatory:



Amanda Lowery

The Reporting Limit (RL) is 5.00 ug Total Pb. Dust wipe area and results are calculated based on area measurements determined by the client. All internal quality control requirements associated with this batch were met, unless otherwise noted.

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, etc., was provided by the client. Results reported above in ug/ft² are calculated based on area supplied by the client. If the report does not contain the result for a field blank, it is due to the fact that the client did not include a field blank with their samples. These sample results do not reflect blank correction. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C.

ELLAP Accreditation through AIHA LAP, LLC (100420), NY ELAP #11714.

Legend	ug = microgram	ug/ft ² = micrograms per square foot	Pb = lead
	mL = milliliter	ft ² = square foot	



ENVIRONMENTAL SERVICES

A Marine Company
LEW Environmental Services P: (800) 783-0567
F: (908) 654-8069

Lead

Chain-of-Custody

24-06-04298



Due Date:
07/02/2024
(Tuesday)
AE

* All wipes.

Project Name: VIOLETA PONCE
 Address: 96 WEST CLINTON STREET
 City, State: DOVER TOWN, NJ
 Project Number: 48977

Sample Type:
 Dust wipe
 Paint chip
 Soil
 TCLP

Turn Around Time (TAT)
 Same Day
 1 Day
 1 Week
 3 Day
 Weekend
 2 Weeks

Name: Danny Kleiman
 Signature: Danny Kleiman

Sample #	Date Collected	Sample Location (Ex: Fl, Kitchen, AC)	Area (inches)	Paint Chip Analysis		
				mg/cm ²	PPM	% wt
96-2-1	06/25/2024	LRFLCC	12 X 12			
96-2-2	06/25/2024	KFLCC	12 X 12			
96-2-3	06/25/2024	BR1FLCC	12 X 12			
96-2-4	06/25/2024	BR2FLCC	12 X 12			
96-2-5	06/25/2024	SFCC	12 X 12			
96-2-6	06/25/2024	LRWSA	33 X 2 3/4			
96-2-7	06/25/2024	KWSB	44 X 3			
96-2-8	06/25/2024	BR1WSA2	32 X 3 1/4			
96-2-9	06/25/2024	BR2WSA2	36 X 7 1/4			

Relinquished by: Danny Kleiman Signature: Danny Kleiman Date/Time: 6/25/24 5:00pm
 Received by: Arnell Williams Signature: Arnell Williams Date/Time: 6/27/24 11:44

96
9