

Company LEW Corporation
 XRF Make Heuresis
 Model Pb200i
 Serial Num. 1830
 Lead concentration units: mg/cm2
 Total Readings: 59
 Action Level 1
 Mode Action Level
 Analytic Mode Paint

All Readings

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
31 U Rose Rita	19682	1.3		TRUE	FALSE	6/24/2024	1:29 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ								
31 U Rose Rita	19683	1.3		TRUE	FALSE	6/24/2024	1:30 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ								
31 U Rose Rita	19684	1.3		TRUE	FALSE	6/24/2024	1:31 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ								
31 U Rose Rita	19685	0.1		TRUE	FALSE	6/24/2024	1:32 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ								
31 U Rose Rita	19686	0.1		TRUE	FALSE	6/24/2024	1:33 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ								
31 U Rose Rita	19687	0.1		TRUE	FALSE	6/24/2024	1:33 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ								
31 U Rose Rita	19688	0	Negative	FALSE	FALSE	6/24/2024	1:35 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Bedroom 1	Window	Casing	Wood	C	1
31 U Rose Rita	19689	-0.1	Negative	FALSE	FALSE	6/24/2024	1:35 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Bedroom 1	Window	Sill	Wood	C	1
31 U Rose Rita	19690	0.1	Negative	FALSE	FALSE	6/24/2024	1:36 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Bedroom 1	Closet	Bi-Fold Door	Wood	C	1
31 U Rose Rita	19691	0.1	Negative	FALSE	FALSE	6/24/2024	1:38 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Bedroom 1	Closet	Wall	Drywall	C	1
31 U Rose Rita	19692	0.2	Negative	FALSE	FALSE	6/24/2024	1:39 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Bedroom 1	Door	---	Wood	B	1
31 U Rose Rita	19693	-0.2	Negative	FALSE	FALSE	6/24/2024	1:40 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Bedroom 1	Door	Casing	Wood	A	1
31 U Rose Rita	19694	0.1	Negative	FALSE	FALSE	6/24/2024	1:40 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Bedroom 1	Door	Jamb	Wood	A	1
31 U Rose Rita	19695	0.1	Negative	FALSE	FALSE	6/24/2024	1:42 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Bedroom 1	Room	Wall	Drywall	A	1
31 U Rose Rita	19696	0.1	Negative	FALSE	FALSE	6/24/2024	1:42 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Bedroom 1	Room	Wall	Drywall	B	1
31 U Rose Rita	19697	-0.2	Negative	FALSE	FALSE	6/24/2024	1:43 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Bedroom 1	Room	Wall	Drywall	C	1
31 U Rose Rita	19698	0.1	Negative	FALSE	FALSE	6/24/2024	1:44 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Bedroom 1	Room	Wall	Drywall	D	1
31 U Rose Rita	19699	0	Negative	FALSE	FALSE	6/24/2024	1:49 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Bedroom 1	Room	Ceiling	Drywall	D	1
31 U Rose Rita	19700	0.1	Negative	FALSE	FALSE	6/24/2024	1:57 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Bedroom 1	Room	Wall	Drywall	A	1
31 U Rose Rita	19701	-0.2	Negative	FALSE	FALSE	6/24/2024	1:58 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Bedroom 1	Room	Baseboard	Wood	A	1
31 U Rose Rita	19702	0	Negative	FALSE	FALSE	6/24/2024	2:02 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Bedroom 1	Room	Baseboard	Wood	A	1
31 U Rose Rita	19703	0	Negative	FALSE	FALSE	6/24/2024	2:03 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Bedroom 2	Room	Baseboard	Wood	B	1
31 U Rose Rita	19704	0.1	Negative	FALSE	FALSE	6/24/2024	2:04 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Bedroom 2	Room	Wall	Drywall	A	1
31 U Rose Rita	19705	0.1	Negative	FALSE	FALSE	6/24/2024	2:04 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Bedroom 2	Room	Wall	Drywall	B	1
31 U Rose Rita	19706	0.1	Negative	FALSE	FALSE	6/24/2024	2:05 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Bedroom 2	Room	Wall	Drywall	C	1
31 U Rose Rita	19707	0.1	Negative	FALSE	FALSE	6/24/2024	2:06 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Bedroom 2	Room	Wall	Drywall	D	1
31 U Rose Rita	19708	-0.1	Negative	FALSE	FALSE	6/24/2024	2:06 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Bedroom 2	Room	Ceiling	Drywall		1
31 U Rose Rita	19709	0	Negative	FALSE	FALSE	6/24/2024	2:07 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Bedroom 2	Closet	Slide Door	Wood	C	1
31 U Rose Rita	19710	0	Negative	FALSE	FALSE	6/24/2024	2:08 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Bedroom 2	Closet	Wall	Drywall	C	1
31 U Rose Rita	19711	0.1	Negative	FALSE	FALSE	6/24/2024	2:09 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Bedroom 2	Closet	Shelf	Wood	C	1
31 U Rose Rita	19712	0.1	Negative	FALSE	FALSE	6/24/2024	2:10 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Bedroom 2	Closet	Door Jamb	Drywall	C	1
31 U Rose Rita	19713	0	Negative	FALSE	FALSE	6/24/2024	2:11 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Bedroom 2	Window	Sill	Wood	C	1
31 U Rose Rita	19714	0	Negative	FALSE	FALSE	6/24/2024	2:12 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Bedroom 2	Window	Casing	Wood	A	1
31 U Rose Rita	19715	0	Negative	FALSE	FALSE	6/24/2024	2:13 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Bedroom 2	Door	Jamb	Wood	D	1
31 U Rose Rita	19716	0	Negative	FALSE	FALSE	6/24/2024	2:14 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Bedroom 2	Door	Jamb	Wood	D	1
31 U Rose Rita	19717	0	Negative	FALSE	FALSE	6/24/2024	2:15 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Bedroom 2	Door	Casing	Wood	D	1
31 U Rose Rita	19718	-0.2	Negative	FALSE	FALSE	6/24/2024	2:16 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Bathroom	Door	Casing	Wood	B	1
31 U Rose Rita	19719	0	Negative	FALSE	FALSE	6/24/2024	2:17 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Bathroom	Door	Jamb	Wood	B	1
31 U Rose Rita	19720	-0.1	Negative	FALSE	FALSE	6/24/2024	2:17 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Bathroom	Door	---	Wood	B	1
31 U Rose Rita	19721	0.1	Negative	FALSE	FALSE	6/24/2024	2:18 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Bathroom	Room	Wall	Drywall	A	1
31 U Rose Rita	19722	0.1	Negative	FALSE	FALSE	6/24/2024	2:19 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Bathroom	Room	Wall	Drywall	B	1
31 U Rose Rita	19723	0.1	Negative	FALSE	FALSE	6/24/2024	2:20 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Bathroom	Room	Wall	Drywall	C	1
31 U Rose Rita	19724	-0.2	Negative	FALSE	FALSE	6/24/2024	2:20 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Bathroom	Room	Wall	Drywall	D	1
31 U Rose Rita	19725	-0.2	Negative	FALSE	FALSE	6/24/2024	2:21 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Bathroom	Room	Baseboard	Wood	B	1
31 U Rose Rita	19726	-0.2	Negative	FALSE	FALSE	6/24/2024	2:22 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Living Room/Dining Room	Room	Baseboard	Wood	C	1
31 U Rose Rita	19727	0	Negative	FALSE	FALSE	6/24/2024	2:23 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Living Room/Dining Room	Window	Sill	Wood	A	1
31 U Rose Rita	19728	-0.1	Negative	FALSE	FALSE	6/24/2024	2:24 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Living Room/Dining Room	Window	Jamb	Wood	A	1
31 U Rose Rita	19729	-0.1	Negative	FALSE	FALSE	6/24/2024	2:25 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Living Room/Dining Room	Closet	Door	Wood	B	1
31 U Rose Rita	19730	0	Negative	FALSE	FALSE	6/24/2024	2:26 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Living Room/Dining Room	Closet	Door Casing	Wood	B	1
31 U Rose Rita	19731	0	Negative	FALSE	FALSE	6/24/2024	2:27 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Living Room/Dining Room	Closet	Door Jamb	Wood	B	1
31 U Rose Rita	19732	0.1	Negative	FALSE	FALSE	6/24/2024	2:28 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Living Room/Dining Room	Closet	Shelf Support	Wood	B	1
31 U Rose Rita	19733	0.1	Negative	FALSE	FALSE	6/24/2024	2:29 PM	Nyire Edmonds-Grant	Paint	31U Rose Rita Terrace, Hammonton, NJ	Unit		Living Room/Dining Room	Room	Wall	Drywall	A	1

Company LEW Corporation
XRF Make Heuresis
Model Pb200i
Serial Num. 1830

Lead concentration units: mg/cm2

Total Readings: 59 Total Positives 0

Action Level 1

Mode Action Level

Analytic Mode Paint

Actionables

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
No Actionables																		