

Company LEW Corporation  
 XRF Make Heuresis  
 Model Pb200i  
 Serial Num. 2128  
 Lead concentration units: mg/cm2  
 Total Readings: 67  
 Action Level 1  
 Mode Action Level  
 Analytic Mode Paint

All Readings

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
7021708	23922	1		TRUE	FALSE	7/2/2024	5:09 PM	Danny Feliciano	Paint	709 Tampa Rd								
7021708	23923	1		TRUE	FALSE	7/2/2024	5:10 PM	Danny Feliciano	Paint	709 Tampa Rd								
7021708	23924	0.8		TRUE	FALSE	7/2/2024	5:11 PM	Danny Feliciano	Paint	709 Tampa Rd								
7021708	23925	0		TRUE	FALSE	7/2/2024	5:12 PM	Danny Feliciano	Paint	709 Tampa Rd								
7021708	23926	0		TRUE	FALSE	7/2/2024	5:12 PM	Danny Feliciano	Paint	709 Tampa Rd								
7021708	23927	-0.1		TRUE	FALSE	7/2/2024	5:12 PM	Danny Feliciano	Paint	709 Tampa Rd								
7021708	23928	-0.1	Negative	FALSE	FALSE	7/2/2024	5:13 PM	Danny Feliciano	Paint	709 Tampa Rd	Unit		Living Room/Dining Room	Door	---	Wood	A	
7021708	23929	-0.9	Negative	FALSE	TRUE	7/2/2024	5:14 PM	Danny Feliciano	Paint	709 Tampa Rd	Unit		Living Room/Dining Room	Door	Casing	Wood	A	
7021708	23930	-0.1	Negative	FALSE	FALSE	7/2/2024	5:14 PM	Danny Feliciano	Paint	709 Tampa Rd	Unit		Living Room/Dining Room	Room	Baseboard	Wood	A	
7021708	23931	-0.6	Negative	FALSE	TRUE	7/2/2024	5:15 PM	Danny Feliciano	Paint	709 Tampa Rd	Unit		Living Room/Dining Room	Window	Casing	Wood	A	
7021708	23932	-0.6	Negative	FALSE	TRUE	7/2/2024	5:15 PM	Danny Feliciano	Paint	709 Tampa Rd	Unit		Living Room/Dining Room	Window	Sill	Wood	A	
7021708	23933	-0.7	Negative	FALSE	TRUE	7/2/2024	5:16 PM	Danny Feliciano	Paint	709 Tampa Rd	Unit		Living Room/Dining Room	Door	Casing	Wood	B	
7021708	23934	-0.6	Negative	FALSE	TRUE	7/2/2024	5:16 PM	Danny Feliciano	Paint	709 Tampa Rd	Unit		Living Room/Dining Room	Closet	Slide Door	Wood	D	
7021708	23935	-0.5	Negative	FALSE	TRUE	7/2/2024	5:17 PM	Danny Feliciano	Paint	709 Tampa Rd	Unit		Living Room/Dining Room	Closet	Door Casing	Wood	D	
7021708	23936	0.2	Negative	FALSE	FALSE	7/2/2024	5:18 PM	Danny Feliciano	Paint	709 Tampa Rd	Unit		Living Room/Dining Room	Room	Ceiling	Drywall		
7021708	23937	-0.4	Negative	FALSE	TRUE	7/2/2024	5:18 PM	Danny Feliciano	Paint	709 Tampa Rd	Unit		Living Room/Dining Room	Door	Casing	Wood	C	
7021708	23938	-0.6	Negative	FALSE	TRUE	7/2/2024	5:19 PM	Danny Feliciano	Paint	709 Tampa Rd	Unit		Living Room/Dining Room	Door	Jamb	Wood	C	
7021708	23939	-1	Negative	FALSE	TRUE	7/2/2024	5:19 PM	Danny Feliciano	Paint	709 Tampa Rd	Unit		Living Room/Dining Room	Door	---	Wood	C	
7021708	23940	-0.7	Negative	FALSE	TRUE	7/2/2024	5:20 PM	Danny Feliciano	Paint	709 Tampa Rd	Unit		Living Room/Dining Room	Room	Wall	Drywall	D	
7021708	23941	-0.1	Negative	FALSE	FALSE	7/2/2024	5:20 PM	Danny Feliciano	Paint	709 Tampa Rd	Unit		Living Room/Dining Room	Room	Wall	Drywall	C	
7021708	23942	-0.5	Negative	FALSE	TRUE	7/2/2024	5:21 PM	Danny Feliciano	Paint	709 Tampa Rd	Unit		Living Room/Dining Room	Room	Wall	Drywall	B	
7021708	23943	-0.8	Negative	FALSE	TRUE	7/2/2024	5:22 PM	Danny Feliciano	Paint	709 Tampa Rd	Unit		Living Room/Dining Room	Room	Wall	Drywall	A	
7021708	23944	0	Negative	FALSE	FALSE	7/2/2024	5:23 PM	Danny Feliciano	Paint	709 Tampa Rd	Unit		Kitchen	Room	Wall	Drywall	A	
7021708	23945	-0.1	Negative	FALSE	FALSE	7/2/2024	5:23 PM	Danny Feliciano	Paint	709 Tampa Rd	Unit		Kitchen	Room	Wall	Drywall	D	
7021708	23946	-0.7	Negative	FALSE	TRUE	7/2/2024	5:24 PM	Danny Feliciano	Paint	709 Tampa Rd	Unit		Kitchen	Room	Wall	Drywall	C	
7021708	23947	-0.7	Negative	FALSE	TRUE	7/2/2024	5:24 PM	Danny Feliciano	Paint	709 Tampa Rd	Unit		Kitchen	Window	Casing	Wood	D	
7021708	23948	-0.1	Negative	FALSE	FALSE	7/2/2024	5:25 PM	Danny Feliciano	Paint	709 Tampa Rd	Unit		Kitchen	Cabinets	Frame	Wood	C	
7021708	23949	-0.6	Negative	FALSE	TRUE	7/2/2024	5:25 PM	Danny Feliciano	Paint	709 Tampa Rd	Unit		Kitchen	Room	Baseboard	Wood	A	
7021708	23950	-0.6	Negative	FALSE	TRUE	7/2/2024	5:26 PM	Danny Feliciano	Paint	709 Tampa Rd	Unit		Kitchen	Door	Casing	Wood	A	
7021708	23951	-0.1	Negative	FALSE	FALSE	7/2/2024	5:26 PM	Danny Feliciano	Paint	709 Tampa Rd	Unit		Kitchen	Door	Jamb	Wood	A	
7021708	23952	-0.9	Negative	FALSE	TRUE	7/2/2024	5:27 PM	Danny Feliciano	Paint	709 Tampa Rd	Unit		Kitchen	Door	---	Wood	A	
7021708	23953	-0.1	Negative	FALSE	FALSE	7/2/2024	5:28 PM	Danny Feliciano	Paint	709 Tampa Rd	Unit		Kitchen	Room	Ceiling	Drywall		
7021708	23954	-0.2	Negative	FALSE	FALSE	7/2/2024	5:28 PM	Danny Feliciano	Paint	709 Tampa Rd	Unit		Bathroom	Room	Ceiling	Drywall		
7021708	23955	-0.7	Negative	FALSE	TRUE	7/2/2024	5:29 PM	Danny Feliciano	Paint	709 Tampa Rd	Unit		Bathroom	Window	Casing	Wood	D	
7021708	23956	-0.7	Negative	FALSE	TRUE	7/2/2024	5:29 PM	Danny Feliciano	Paint	709 Tampa Rd	Unit		Bathroom	Room	Wall	Drywall	D	
7021708	23957	-0.1	Negative	FALSE	FALSE	7/2/2024	5:30 PM	Danny Feliciano	Paint	709 Tampa Rd	Unit		Bathroom	Room	Wall	Drywall	A	
7021708	23958	-1	Negative	FALSE	TRUE	7/2/2024	5:30 PM	Danny Feliciano	Paint	709 Tampa Rd	Unit		Bathroom	Room	Wall	Drywall	B	
7021708	23959	-0.9	Negative	FALSE	TRUE	7/2/2024	5:31 PM	Danny Feliciano	Paint	709 Tampa Rd	Unit		Bathroom	Room	Wall	Drywall	C	
7021708	23960	-0.3	Negative	FALSE	TRUE	7/2/2024	5:33 PM	Danny Feliciano	Paint	709 Tampa Rd	Unit		Bathroom	Room	Baseboard		C	
7021708	23961	-0.1	Negative	FALSE	FALSE	7/2/2024	5:34 PM	Danny Feliciano	Paint	709 Tampa Rd	Unit		Bathroom	Door	---		C	
7021708	23962	0	Negative	FALSE	FALSE	7/2/2024	5:34 PM	Danny Feliciano	Paint	709 Tampa Rd	Unit		Bathroom	Door	Jamb		C	
7021708	23963	-0.4	Negative	FALSE	TRUE	7/2/2024	5:35 PM	Danny Feliciano	Paint	709 Tampa Rd	Unit		Bathroom	Door	Casing		C	
7021708	23964	-0.4	Negative	FALSE	TRUE	7/2/2024	5:36 PM	Danny Feliciano	Paint	709 Tampa Rd	Unit		Bedroom 1	Door	Casing		A	
7021708	23965	-0.7	Negative	FALSE	TRUE	7/2/2024	5:37 PM	Danny Feliciano	Paint	709 Tampa Rd	Unit		Bedroom 1	Door	Jamb		A	



Company LEW Corporation  
XRF Make Heuresis  
Model Pb200i  
Serial Num. 2128

Lead concentration units: mg/cm2

Total Readings: 67 Total Positives 0  
Action Level 1  
Mode Action Level  
Analytic Mode Paint

**Actionables**

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
No Actionables																		