



7469 Whitepine Rd
 North Chesterfield, VA 23237
 Telephone: 800.347.4010

Lead Dust Wipe Analysis Report

Report Number: 24-08-05303

Client: LEW Corp
 181 US Hwy 46
 Mine Hill, NJ 07803

Received Date: 08/29/2024
Analyzed Date: 09/04/2024
Reported Date: 09/04/2024

Project/Test Address: 63327; Dust Wipe Samples; 231 Rt 46 2nd Floor; Mine Hill, NJ
Collection Date: 08/23/2024

Client Number:
 201327

Laboratory Results

Fax Number:
 Ext 18 Melissa

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft ²)	Concentration (ug/ft ²)	Narrative ID
24-08-05303-001	1	SUNROOM	FL	<5.00	1.00	<5.00	
24-08-05303-002	2	BATHROOM	FL	<5.00	1.00	<5.00	
24-08-05303-003	3	BEDROOM 1	FL	<5.00	1.00	<5.00	
24-08-05303-004	4	KITCHEN	FL	7.48	1.00	7.48	
24-08-05303-005	5	BEDROOM 2	FL	<5.00	1.00	<5.00	
24-08-05303-006	6	BATHROOM	SL	<5.00	0.542	<9.23	
24-08-05303-007	7	BEDROOM 1	SL	<5.00	0.542	<9.23	
24-08-05303-008	8	KITCHEN	SL	<5.00	0.542	<9.23	
24-08-05303-009	9	BEDROOM 2	SL	<5.00	0.542	<9.23	

Environmental Hazards Services, L.L.C

Client Number: 201327

Report Number: 24-08-05303

Project/Test Address: 63327; Dust Wipe Samples; 231 Rt 46 2nd Floor;
Mine Hill, NJ

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft ²)	Concentration (ug/ft ²)	Narrative ID
-------------------	----------------------	---------------------	---------	---------------	------------------------------	-------------------------------------	--------------

Method: ASTM E-1979-17/EPA SW846 7000B

Accreditation #:

Reviewed By Authorized Signatory: Candace Mason

Candace Mason

QA Chemist

The Reporting Limit (RL) is 5.00 ug Total Pb. Dust wipe area and results are calculated based on area measurements determined by the client. All internal quality control requirements associated with this batch were met, unless otherwise noted.

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, etc., was provided by the client. Results reported above in ug/ft² are calculated based on area supplied by the client. If the report does not contain the result for a field blank, it is due to the fact that the client did not include a field blank with their samples. These sample results do not reflect blank correction. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C.

ELLAP Accreditation through AIHA LAP, LLC (100420), NY ELAP #11714.

Legend

ug = microgram

ug/ft² = micrograms per square foot

Pb = lead

mL = milliliter

ft² = square foot



ENVIRONMENTAL SERVICES

A Mainline Company
LEW Environmental Services P: (800) 783-0567
F: (908) 654-8069

Lead

Chain-of-Custody



24-08-05303

Due Date:

09/04/2024

(Wednesday)

AE

* All wipe containers must be kept in a cool, dry place.

SI

Project Name: DUST WIPE SAMPLES
Address: 231 Rt 46 2nd Floor
City, State: Mine Hill, NJ
Project Number: 63327

Sample Type
 Dust wipe
 Paint chip
 Soil
 TCLP

Turn Around Time (TAT)
 Same Day
 1 Day
 1 Week
 3 Day
 Weekend
 2 Weeks

Sampler Information
Name: ERICK ULLOA
Signature: *[Signature]*

Sample #	Date Collected	Sample Location (Ex: FI, Kitchen, AC)	Area (inches)	Paint Chip Analysis		
				mg/cm ²	PPM	% wt
1	08/23/2024	Sunroom	12 X 12			
2		Bathroom Floor	12 X 12			
3		Bedroom 1 Floor	12 X 12			
4		Kitchen Floor	12 X 12			
5		Bedroom 2 Floor	12 X 12			
6		Bathroom Sill	26 X 3			
7		Bedroom 1 Floor	26 X 3			
8		Kitchen Floor	26 X 3			
9		Bedroom 2 Sill	26 X 3			

VB

Relinquished by: ERICK ULLOA
Received by: *[Signature]*
Signature: *[Signature]*
Date/Time: 08/23/2024
Date/Time: 8/29/24 3:04pm