

Company LEW Corporation
 XRF Make Heuresis
 Model Pb200i
 Serial Num. 2822
 Lead concentration units: mg/cm2
 Total Readings: 161
 Action Level 1
 Mode Action Level
 Analytic Mode Paint

All Readings

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
7151003	257	1		TRUE	FALSE	7/15/2024	10:03 AM	Alex Salvador	Paint	879 Salem Dr Toms River								
7151003	258	1		TRUE	FALSE	7/15/2024	10:03 AM	Alex Salvador	Paint	879 Salem Dr Toms River								
7151003	259	1		TRUE	FALSE	7/15/2024	10:03 AM	Alex Salvador	Paint	879 Salem Dr Toms River								
7151003	260	0.1		TRUE	FALSE	7/15/2024	10:03 AM	Alex Salvador	Paint	879 Salem Dr Toms River								
7151003	261	0.1		TRUE	FALSE	7/15/2024	10:04 AM	Alex Salvador	Paint	879 Salem Dr Toms River								
7151003	262	0		TRUE	FALSE	7/15/2024	10:04 AM	Alex Salvador	Paint	879 Salem Dr Toms River								
7151003	263	0.1	Negative	FALSE	FALSE	7/15/2024	10:06 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Living Room	Door	---	Metal	A	1
7151003	264	0	Negative	FALSE	FALSE	7/15/2024	10:07 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Living Room	Door	Jamb	Wood	A	1
7151003	265	0.1	Negative	FALSE	FALSE	7/15/2024	10:07 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Living Room	Door	Casing	Wood	A	1
7151003	266	-0.2	Negative	FALSE	FALSE	7/15/2024	10:07 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Living Room	Window	Sill	Wood	A	1
7151003	267	0	Negative	FALSE	FALSE	7/15/2024	10:08 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Living Room	Window	Apron	Wood	A	1
7151003	268	0.1	Negative	FALSE	FALSE	7/15/2024	10:08 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Living Room	Room	Wall	Drywall	A	1
7151003	269	0.3	Negative	FALSE	FALSE	7/15/2024	10:08 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Living Room	Room	Wall	Drywall	B	1
7151003	270	0.1	Negative	FALSE	FALSE	7/15/2024	10:08 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Living Room	Room	Wall	Drywall	C	1
7151003	271	0	Negative	FALSE	FALSE	7/15/2024	10:09 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Living Room	Room	Wall	Drywall	D	1
7151003	272	-0.4	Negative	FALSE	FALSE	7/15/2024	10:09 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Living Room	Room	Baseboard	Wood	D	1
7151003	273	0	Negative	FALSE	FALSE	7/15/2024	10:09 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Living Room	Closet	Door	Wood	A	1
7151003	274	-0.2	Negative	FALSE	FALSE	7/15/2024	10:09 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Living Room	Closet	Door Jamb	Wood	A	1
7151003	275	-0.1	Negative	FALSE	FALSE	7/15/2024	10:10 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Living Room	Closet	Shelf Support	Wood	A	1
7151003	276	0.1	Negative	FALSE	FALSE	7/15/2024	10:10 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Living Room	Closet	Wall	Drywall	A	1
7151003	277	0	Negative	FALSE	FALSE	7/15/2024	10:10 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Living Room	Closet	Baseboard	Wood	A	1
7151003	278	0.1	Negative	FALSE	FALSE	7/15/2024	10:11 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 1	Door	---	Wood	C	1
7151003	279	-0.1	Negative	FALSE	FALSE	7/15/2024	10:11 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 1	Door	Jamb	Wood	C	1
7151003	280	0	Negative	FALSE	FALSE	7/15/2024	10:11 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 1	Door	Casing	Wood	C	1
7151003	281	0.1	Negative	FALSE	FALSE	7/15/2024	10:12 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 1	Closet	Door	Wood	C	1
7151003	282	0.1	Negative	FALSE	FALSE	7/15/2024	10:12 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 1	Closet	Door Jamb	Wood	C	1
7151003	283	0	Negative	FALSE	FALSE	7/15/2024	10:12 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 1	Closet	Door Casing	Wood	C	1
7151003	284	0	Negative	FALSE	FALSE	7/15/2024	10:12 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 1	Closet	Shelf Support	Wood	C	1
7151003	285	0	Negative	FALSE	FALSE	7/15/2024	10:12 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 1	Closet	Shelf	Wood	C	1
7151003	286	0.1	Negative	FALSE	FALSE	7/15/2024	10:13 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 1	Closet	Wall	Drywall	C	1
7151003	287	-0.1	Negative	FALSE	FALSE	7/15/2024	10:13 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 1	Window	Sill	Wood	B	1
7151003	288	0.2	Negative	FALSE	FALSE	7/15/2024	10:13 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 1	Room	Wall	Drywall	B	1
7151003	289	0.2	Negative	FALSE	FALSE	7/15/2024	10:14 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 1	Room	Wall	Drywall	C	1
7151003	290	0.2	Negative	FALSE	FALSE	7/15/2024	10:14 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 1	Room	Wall	Drywall	D	1
7151003	291	0.2	Negative	FALSE	FALSE	7/15/2024	10:14 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 1	Room	Wall	Drywall	A	1
7151003	292	-0.2	Negative	FALSE	FALSE	7/15/2024	10:15 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 1	Room	Baseboard	Wood	D	1
7151003	293	0	Negative	FALSE	FALSE	7/15/2024	10:15 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 2	Room	Baseboard	Wood	D	1
7151003	294	0.2	Negative	FALSE	FALSE	7/15/2024	10:15 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 2	Room	Wall	Drywall	D	1
7151003	295	0.3	Negative	FALSE	FALSE	7/15/2024	10:16 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 2	Room	Wall	Drywall	A	1
7151003	296	0.2	Negative	FALSE	FALSE	7/15/2024	10:16 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 2	Room	Wall	Drywall	B	1
7151003	297	0	Negative	FALSE	FALSE	7/15/2024	10:16 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 2	Room	Wall	Drywall	C	1
7151003	298	-0.3	Negative	FALSE	FALSE	7/15/2024	10:16 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 2	Window	Sill	Wood	B	1
7151003	299	-0.1	Negative	FALSE	FALSE	7/15/2024	10:17 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 2	Window	Apron	Wood	B	1
7151003	300	0.1	Negative	FALSE	FALSE	7/15/2024	10:17 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 2	Door	---	Wood	D	1
7151003	301	-0.2	Negative	FALSE	FALSE	7/15/2024	10:17 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 2	Door	Jamb	Wood	D	1

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
7151003	302	0.1	Negative	FALSE	FALSE	7/15/2024	10:17 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 2	Door	Casing	Wood	D	1
7151003	303	0.1	Negative	FALSE	FALSE	7/15/2024	10:18 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 2	Closet	Door	Wood	A	1
7151003	304	-0.1	Negative	FALSE	FALSE	7/15/2024	10:18 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 2	Closet	Door Jamb	Wood	A	1
7151003	305	-0.3	Negative	FALSE	FALSE	7/15/2024	10:18 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 2	Closet	Door Casing	Wood	A	1
7151003	306	-0.1	Negative	FALSE	FALSE	7/15/2024	10:18 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 2	Closet	Shelf Support	Wood	A	1
7151003	307	-0.2	Negative	FALSE	FALSE	7/15/2024	10:19 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 2	Closet	Shelf	Wood	A	1
7151003	308	0.1	Negative	FALSE	FALSE	7/15/2024	10:19 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bathroom	Door	---	Wood	A	1
7151003	309	0	Negative	FALSE	FALSE	7/15/2024	10:19 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bathroom	Door	Jamb	Wood	A	1
7151003	310	-0.2	Negative	FALSE	FALSE	7/15/2024	10:20 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bathroom	Door	Casing	Wood	A	1
7151003	311	0	Negative	FALSE	FALSE	7/15/2024	10:20 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bathroom	Cabinets	Door	Wood	D	1
7151003	312	0.1	Negative	FALSE	FALSE	7/15/2024	10:20 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bathroom	Cabinets	Frame	Wood	D	1
7151003	313	0.1	Negative	FALSE	FALSE	7/15/2024	10:21 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bathroom	Room	Wall	Drywall	D	1
7151003	314	0.1	Negative	FALSE	FALSE	7/15/2024	10:21 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bathroom	Room	Wall	Drywall	A	1
7151003	315	0	Negative	FALSE	FALSE	7/15/2024	10:21 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bathroom	Room	Wall	Drywall	B	1
7151003	316	0	Negative	FALSE	FALSE	7/15/2024	10:21 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bathroom	Room	Wall	Drywall	C	1
7151003	317	0	Negative	FALSE	FALSE	7/15/2024	10:21 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bathroom	Room	Ceiling	Drywall	C	1
7151003	318	0.1	Negative	FALSE	FALSE	7/15/2024	10:22 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bathroom	Window	Jamb	Wood	C	1
7151003	319	0	Negative	FALSE	FALSE	7/15/2024	10:22 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bathroom	Room	Baseboard	Wood	B	1
7151003	320	0.2	Negative	FALSE	FALSE	7/15/2024	10:22 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bathroom	Register	---	Metal	B	1
7151003	321	0.1	Negative	FALSE	FALSE	7/15/2024	10:23 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Hall	Closet	Door	Wood	D	1
7151003	322	-0.2	Negative	FALSE	FALSE	7/15/2024	10:23 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Hall	Closet	Door Jamb	Wood	D	1
7151003	323	-0.1	Negative	FALSE	FALSE	7/15/2024	10:23 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Hall	Closet	Door Casing	Wood	D	1
7151003	324	-0.2	Negative	FALSE	FALSE	7/15/2024	10:23 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Hall	Closet	Shelf Support	Wood	D	1
7151003	325	-0.1	Negative	FALSE	FALSE	7/15/2024	10:24 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Hall	Closet	Shelf	Wood	D	1
7151003	326	0.1	Negative	FALSE	FALSE	7/15/2024	10:24 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Hall	Closet	Wall	Drywall	D	1
7151003	327	0.1	Negative	FALSE	FALSE	7/15/2024	10:24 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Hall	Room	Wall	Drywall	D	1
7151003	328	-0.1	Negative	FALSE	FALSE	7/15/2024	10:24 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Hall	Room	Wall	Drywall	C	1
7151003	329	-0.1	Negative	FALSE	FALSE	7/15/2024	10:25 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Hall	Room	Wall	Drywall	B	1
7151003	330	0.2	Negative	FALSE	FALSE	7/15/2024	10:25 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Hall	Room	Wall	Drywall	A	1
7151003	331	-0.1	Negative	FALSE	FALSE	7/15/2024	10:25 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Hall	Room	Baseboard	Wood	C	1
7151003	332	0	Negative	FALSE	FALSE	7/15/2024	10:26 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Rear Entry	Room	Baseboard	Wood	D	1
7151003	333	0.2	Negative	FALSE	FALSE	7/15/2024	10:26 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Rear Entry	Room	Wall	Drywall	D	1
7151003	334	0.1	Negative	FALSE	FALSE	7/15/2024	10:26 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Rear Entry	Room	Wall	Drywall	C	1
7151003	335	0.1	Negative	FALSE	FALSE	7/15/2024	10:27 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Rear Entry	Room	Wall	Drywall	B	1
7151003	336	0.1	Negative	FALSE	FALSE	7/15/2024	10:27 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Rear Entry	Room	Wall	Drywall	A	1
7151003	337	0.2	Negative	FALSE	FALSE	7/15/2024	10:27 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Rear Entry	Room	Ceiling	Drywall	A	1
7151003	338	0.1	Negative	FALSE	FALSE	7/15/2024	10:27 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Rear Entry	Door	---	Metal	C	1
7151003	339	0	Negative	FALSE	FALSE	7/15/2024	10:28 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Rear Entry	Door	Jamb	Wood	C	1
7151003	340	0.1	Negative	FALSE	FALSE	7/15/2024	10:28 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Rear Entry	Door	Casing	Wood	C	1
7151003	341	-0.2	Negative	FALSE	FALSE	7/15/2024	10:28 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Kitchen	Window	Sill	Wood	C	1
7151003	342	0	Negative	FALSE	FALSE	7/15/2024	10:29 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Kitchen	Window	Jamb	Wood	C	1
7151003	343	-0.1	Negative	FALSE	FALSE	7/15/2024	10:29 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Kitchen	Window	Casing	Wood	C	1
7151003	344	0	Negative	FALSE	FALSE	7/15/2024	10:29 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Kitchen	Cabinets	Door	Wood	C	1
7151003	345	0.1	Negative	FALSE	FALSE	7/15/2024	10:29 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Kitchen	Cabinets	Frame	Wood	C	1
7151003	346	0.2	Negative	FALSE	FALSE	7/15/2024	10:30 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Kitchen	Room	Wall	Drywall	C	1
7151003	347	0.1	Negative	FALSE	FALSE	7/15/2024	10:30 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Kitchen	Room	Wall	Drywall	B	1
7151003	348	0	Negative	FALSE	FALSE	7/15/2024	10:30 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Kitchen	Room	Baseboard	Wood	B	1
7151003	349	0.2	Negative	FALSE	FALSE	7/15/2024	10:30 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Kitchen	Room	Wall	Drywall	A	1
7151003	350	0.1	Negative	FALSE	FALSE	7/15/2024	10:31 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Kitchen	Room	Wall	Drywall	D	1
7151003	351	0	Negative	FALSE	FALSE	7/15/2024	10:31 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Dining Room	Room	Wall	Drywall	B	1
7151003	352	0	Negative	FALSE	FALSE	7/15/2024	10:31 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Dining Room	Room	Wall	Drywall	C	1
7151003	353	-0.1	Negative	FALSE	FALSE	7/15/2024	10:31 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Dining Room	Room	Wall	Drywall	D	1
7151003	354	0	Negative	FALSE	FALSE	7/15/2024	10:32 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Dining Room	Room	Wall	Drywall	A	1
7151003	355	-0.2	Negative	FALSE	FALSE	7/15/2024	10:32 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Dining Room	Room	Baseboard	Wood	A	1
7151003	356	-0.2	Negative	FALSE	FALSE	7/15/2024	10:32 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Dining Room	Window	Jamb	Wood	A	1

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
7151003	357	-0.3	Negative	FALSE	FALSE	7/15/2024	10:32 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Dining Room	Window	Casing	Wood	A	1
7151003	358	0	Negative	FALSE	FALSE	7/15/2024	10:33 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Dining Room	Room	Wall	Drywall	B	1
7151003	359	-0.2	Negative	FALSE	FALSE	7/15/2024	10:33 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Dining Room	Room	Baseboard	Wood	D	1
7151003	360	0.1	Negative	FALSE	FALSE	7/15/2024	10:33 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Dining Room	Door	---	Wood	D	1
7151003	361	0.1	Negative	FALSE	FALSE	7/15/2024	10:34 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Dining Room	Door	Jamb	Wood	D	1
7151003	362	0	Negative	FALSE	FALSE	7/15/2024	10:34 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Dining Room	Door	Casing	Wood	D	1
7151003	363	0.1	Negative	FALSE	FALSE	7/15/2024	10:35 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Living Room	Room	Ceiling	Drywall	D	1
7151003	364	0.1	Negative	FALSE	FALSE	7/15/2024	10:35 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Hall	Room	Ceiling	Drywall	D	1
7151003	365	0.1	Negative	FALSE	FALSE	7/15/2024	10:35 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 1	Room	Ceiling	Drywall	D	1
7151003	366	0.1	Negative	FALSE	FALSE	7/15/2024	10:36 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 2	Room	Ceiling	Drywall	D	1
7151003	367	0	Negative	FALSE	FALSE	7/15/2024	10:36 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bathroom	Room	Ceiling	Drywall	D	1
7151003	368	0.1	Negative	FALSE	FALSE	7/15/2024	10:36 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Kitchen	Room	Ceiling	Drywall	D	1
7151003	369	0.1	Negative	FALSE	FALSE	7/15/2024	10:37 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Dining Room	Room	Ceiling	Drywall	D	1
7151003	370	0.1	Negative	FALSE	FALSE	7/15/2024	10:37 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bathroom 2	Room	Ceiling	Drywall	D	1
7151003	371	0.1	Negative	FALSE	FALSE	7/15/2024	10:38 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bathroom 2	Room	Wall	Drywall	B	1
7151003	372	0.1	Negative	FALSE	FALSE	7/15/2024	10:38 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bathroom 2	Room	Wall	Drywall	C	1
7151003	373	0.1	Negative	FALSE	FALSE	7/15/2024	10:38 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bathroom 2	Room	Wall	Drywall	D	1
7151003	374	0.1	Negative	FALSE	FALSE	7/15/2024	10:38 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bathroom 2	Room	Wall	Drywall	A	1
7151003	375	0.1	Negative	FALSE	FALSE	7/15/2024	10:39 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bathroom 2	Door	---	Wood	A	1
7151003	376	-0.2	Negative	FALSE	FALSE	7/15/2024	10:39 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bathroom 2	Door	Jamb	Wood	A	1
7151003	377	-0.1	Negative	FALSE	FALSE	7/15/2024	10:39 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bathroom 2	Door	Casing	Wood	A	1
7151003	378	-0.2	Negative	FALSE	FALSE	7/15/2024	10:39 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bathroom 2	Room	Baseboard	Wood	B	1
7151003	379	0.1	Negative	FALSE	FALSE	7/15/2024	10:40 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bathroom 2	Cabinets	Door	Wood	D	1
7151003	380	0	Negative	FALSE	FALSE	7/15/2024	10:40 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bathroom 2	Cabinets	Frame	Wood	D	1
7151003	381	0.1	Negative	FALSE	FALSE	7/15/2024	10:41 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		2nd Floor Hallway	Room	Wall	Drywall	D	1
7151003	382	0.1	Negative	FALSE	FALSE	7/15/2024	10:41 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		2nd Floor Hallway	Room	Wall	Drywall	A	1
7151003	383	0	Negative	FALSE	FALSE	7/15/2024	10:41 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		2nd Floor Hallway	Room	Wall	Drywall	B	1
7151003	384	0	Negative	FALSE	FALSE	7/15/2024	10:41 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		2nd Floor Hallway	Room	Wall	Drywall	C	1
7151003	385	-0.1	Negative	FALSE	FALSE	7/15/2024	10:42 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		2nd Floor Hallway	Room	Baseboard	Wood	C	1
7151003	386	0	Negative	FALSE	FALSE	7/15/2024	10:42 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 4	Door	---	Wood	C	1
7151003	387	0	Negative	FALSE	FALSE	7/15/2024	10:42 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 4	Door	Jamb	Wood	C	1
7151003	388	-0.2	Negative	FALSE	FALSE	7/15/2024	10:43 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 4	Door	Casing	Wood	C	1
7151003	389	0.2	Negative	FALSE	FALSE	7/15/2024	10:43 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 4	Room	Wall	Drywall	C	1
7151003	390	-0.2	Negative	FALSE	FALSE	7/15/2024	10:43 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 4	Room	Baseboard	Wood	C	1
7151003	391	0	Negative	FALSE	FALSE	7/15/2024	10:44 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 4	Room	Wall	Drywall	B	1
7151003	392	0.1	Negative	FALSE	FALSE	7/15/2024	10:44 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 4	Room	Wall	Drywall	D	1
7151003	393	0	Negative	FALSE	FALSE	7/15/2024	10:44 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 4	Window	Jamb	Wood	D	1
7151003	394	0	Negative	FALSE	FALSE	7/15/2024	10:44 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 4	Window	Casing	Wood	D	1
7151003	395	-0.1	Negative	FALSE	FALSE	7/15/2024	10:45 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 4	Closet	Shelf Support	Wood	A	1
7151003	396	0	Negative	FALSE	FALSE	7/15/2024	10:45 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 4	Closet	Shelf	Wood	A	1
7151003	397	-0.1	Negative	FALSE	FALSE	7/15/2024	10:45 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 4	Closet	Wall	Wood	A	1
7151003	398	0.1	Negative	FALSE	FALSE	7/15/2024	10:46 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 4	Room	Wall	Drywall	A	1
7151003	399	0.1	Negative	FALSE	FALSE	7/15/2024	10:46 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 4	Room	Wall	Drywall	B	1
7151003	400	0	Negative	FALSE	FALSE	7/15/2024	10:46 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 4	Room	Ceiling	Drywall	B	1
7151003	401	0.1	Negative	FALSE	FALSE	7/15/2024	10:46 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		2nd Floor Hallway	Room	Ceiling	Drywall	B	1
7151003	402	-0.3	Negative	FALSE	FALSE	7/15/2024	10:47 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 3	Door	---	Wood	D	1
7151003	403	-0.3	Negative	FALSE	FALSE	7/15/2024	10:47 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 3	Door	Jamb	Wood	D	1
7151003	404	-0.1	Negative	FALSE	FALSE	7/15/2024	10:47 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 3	Door	Casing	Wood	D	1
7151003	405	0.1	Negative	FALSE	FALSE	7/15/2024	10:48 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 3	Room	Wall	Drywall	D	1
7151003	406	0	Negative	FALSE	FALSE	7/15/2024	10:48 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 3	Room	Wall	Drywall	A	1
7151003	407	0.1	Negative	FALSE	FALSE	7/15/2024	10:48 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 3	Room	Wall	Drywall	C	1
7151003	408	0.1	Negative	FALSE	FALSE	7/15/2024	10:48 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 3	Room	Wall	Drywall	B	1
7151003	409	-0.3	Negative	FALSE	FALSE	7/15/2024	10:49 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 3	Window	Jamb	Wood	B	1
7151003	410	-0.1	Negative	FALSE	FALSE	7/15/2024	10:49 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 3	Window	Casing	Wood	B	1
7151003	411	0.1	Negative	FALSE	FALSE	7/15/2024	10:49 AM	Alex Salvador	Paint	879 Salem Dr Toms River	Unit		Bedroom 3	Closet	Door	Wood	A	1

Company LEW Corporation
XRF Make Heuresis
Model Pb200i
Serial Num. 2822

Lead concentration units: mg/cm2
Total Readings: 161 Total Positives 0
Action Level 1
Mode Action Level
Analytic Mode Paint

Actionables

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
No Actionables																		