



7469 Whitepine Rd
 North Chesterfield, VA 23237
 Telephone: 800.347.4010

Lead Dust Wipe Analysis Report

Report Number: 24-09-02417

Client: LEW Corp
 181 US Hwy 46
 Mine Hill, NJ 07803

Received Date: 09/13/2024
Analyzed Date: 09/17/2024
Reported Date: 09/18/2024

Project/Test Address: 64517; Dust Wipe Sampling; 209 Shafer Ave Unit 1; Phillipsburg, NJ

Collection Date: 09/11/2024

Client Number:
 201327

Laboratory Results

Fax Number:
 Ext 18 Melissa

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft ²)	Concentration (ug/ft ²)	Narrative ID
24-09-02417-001	1	SUNROOM AC	FL	<5.00	1.00	<5.00	
24-09-02417-002	2	2ND FLOOR HALLWAY AC	FL	<5.00	1.00	<5.00	
24-09-02417-003	3	FOYER AC	FL	<5.00	1.00	<5.00	
24-09-02417-004	4	KITCHEN AC	FL	<5.00	1.00	<5.00	
24-09-02417-005	5	BEDROOM 1 BC	FL	<5.00	1.00	<5.00	
24-09-02417-006	6	BEDROOM 3 CC	FL	<5.00	1.00	<5.00	
24-09-02417-007	7	FOYER AC	SL	<5.00	0.846	<5.92	
24-09-02417-008	8	KITCHEN CC	SL	<5.00	2.43	<2.06	
24-09-02417-009	9	BEDROOM 1 DC	SL	<5.00	0.681	<7.35	
24-09-02417-010	10	BEDROOM 3 AC	SL	<5.00	0.681	<7.35	

Environmental Hazards Services, L.L.C

Client Number: 201327

Report Number: 24-09-02417

Project/Test Address: 64517; Dust Wipe Sampling; 209 Shafer Ave Unit 1;
Phillipsburg, NJ

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft ²)	Concentration (ug/ft ²)	Narrative ID
-------------------	----------------------	---------------------	---------	---------------	------------------------------	-------------------------------------	--------------

Method: ASTM E-1979-17/EPA SW846 7000B

Accreditation #:

Reviewed By Authorized Signatory: Melissa Kanode

Melissa Kanode

QA/QC Clerk

The Reporting Limit (RL) is 5.00 ug Total Pb. Dust wipe area and results are calculated based on area measurements determined by the client. All internal quality control requirements associated with this batch were met, unless otherwise noted.

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, etc., was provided by the client. Results reported above in ug/ft² are calculated based on area supplied by the client. If the report does not contain the result for a field blank, it is due to the fact that the client did not include a field blank with their samples. These sample results do not reflect blank correction. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C.

ELLAP Accreditation through AIHA LAP, LLC (100420), NY ELAP #11714.

Legend	ug = microgram	ug/ft ² = micrograms per square foot	Pb = lead
	mL = milliliter	ft ² = square foot	



ENVIRONMENTAL SERVICES

A Mainline Company
LEW Environmental Services P: (800) 783-0567
F: (908) 654-8069

Lead

Chain-of-Custody

24-09-02417



Due Date:
09/18/2024
(Wednesday)
AE

10+

* All Wipes Submitted meet ASTM E1724 Requirements.

Project Name: Dust wipe sampling
 Address: 209 Strafer Ave unit 1
 City, State: Philadelphia PA
 Project Number: Order # 64517

Sample Type
 Dust wipe
 Paint chip
 Soil
 TCLP

Turn Around Time (TAT)
 Same Day
 1 Day
 1 Week
 3 Day
 Weekend
 2 Weeks

Sampler Information
 Name: _____
 Signature: _____

Sample #	Date Collected	Sample Location (Ex: Fl, Kitchen, AC)	Area (inches)	Paint Chip Analysis		
				mg/cm ²	PPM	% wt
1	09-11-24	Floor Sun Room AC	12 X 12			
2		Floor 2nd floor hallway	12 X 12			
3		Floor foyer AC	12 X 12			
4		Floor kitchen AC	12 X 12			
5		Floor Bedroom 1 BC	12 X 12			
6		Floor Bedroom 3 CC	12 X 12			
2		w/fin Foyer AC	32 1/2 X 33 1/4			
8		w/fin 1/4 Kitchen CC	25 X 14			
9		w/fin Bedroom 1 AC	28 X 3 1/2			
10		w/fin Bedroom 3 AC	28 X 3 1/2			
			X			

Relinquished by: Yvesi Heubia Signature: Yvesi Heubia Date/Time: 09-11-24 9:21 am
 Received by: SARASWATI Signature: [Signature] Date/Time: 9/15/24 4:18 pm