



7469 Whitepine Rd
 North Chesterfield, VA 23237
 Telephone: 800.347.4010

Lead Dust Wipe Analysis Report

Report Number: 24-09-02564

Client: LEW Corp
 181 US Hwy 46
 Mine Hill, NJ 07803

Received Date: 09/16/2024
Analyzed Date: 09/18/2024
Reported Date: 09/19/2024

Project/Test Address: 64717; Dust Wipe Sampling; 730 W Front St; Plainfield, NJ

Collection Date: 09/12/2024

Client Number:
 201327

Laboratory Results

Fax Number:
 Ext 18 Melissa

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft ²)	Concentration (ug/ft ²)	Narrative ID
24-09-02564-001	1	SUNROOM AC	FL	<5.00	1.00	<5.00	
24-09-02564-002	2	BEDROOM 1 AC	FL	<5.00	1.00	<5.00	
24-09-02564-003	3	KITCHEN AC	FL	<5.00	1.00	<5.00	
24-09-02564-004	4	BEDROOM 3 BC	FL	<5.00	1.00	<5.00	
24-09-02564-005	5	BEDROOM 4 AC	FL	<5.00	1.00	<5.00	
24-09-02564-006	6	HALLWAY 2 AC	FL	<5.00	1.00	<5.00	
24-09-02564-007	7	BEDROOM 1 DC	SL	<5.00	0.208	<24.1	
24-09-02564-008	8	KITCHEN BC	SL	<5.00	1.11	<4.51	
24-09-02564-009	9	BEDROOM 3 CC	SL	<5.00	0.486	<10.3	
24-09-02564-010	10	BEDROOM 4 AR	SL	<5.00	0.556	<9.00	

Environmental Hazards Services, L.L.C

Client Number: 201327

Report Number: 24-09-02564

Project/Test Address: 64717; Dust Wipe Sampling; 730 W Front St;
Plainfield, NJ

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft ²)	Concentration (ug/ft ²)	Narrative ID
-------------------	----------------------	---------------------	---------	---------------	------------------------------	-------------------------------------	--------------

Method: ASTM E-1979-17/EPA SW846 7000B

Accreditation #:

Reviewed By Authorized Signatory: Candace Mason
Candace Mason
QA Chemist

The Reporting Limit (RL) is 5.00 ug Total Pb. Dust wipe area and results are calculated based on area measurements determined by the client. All internal quality control requirements associated with this batch were met, unless otherwise noted.

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, etc., was provided by the client. Results reported above in ug/ft² are calculated based on area supplied by the client. If the report does not contain the result for a field blank, it is due to the fact that the client did not include a field blank with their samples. These sample results do not reflect blank correction. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C.

ELLAP Accreditation through AIHA LAP, LLC (100420), NY ELAP #11714.

Legend	ug = microgram	ug/ft ² = micrograms per square foot	Pb = lead
	mL = milliliter	ft ² = square foot	



ENVIRONMENTAL SERVICES

A Mainline Company

LEW Environmental Services P: (800) 783-0567

F: (908) 654-8069

Lead

Chain-of-Custody

24-09-02564



Due Date:
09/19/2024
(Thursday)
AE

* All wipe: 10+

Project Name: Dust wipe sampling
 Address: 730 W Front St
 City, State: Plainfield NJ
 Project Number: Order 64712

Sample Type: Dust wipe Paint chip Soil TCLP

Turn Around Time (TAT): Same Day 1 Day 1 Week 3 Day Weekend 2 Weeks

Name: _____
 Signature: _____

Sampler Information

Sample #	Date Collected	Sample Location (Ex: Fl, Kitchen, AC)	Area (inches)	Paint Chip Analysis		
				mg/cm ²	PPM	% wt
1	09-12-24	Floor Sun Room AC	12 x 12			
2		Floor Bedroom 1 AC	12 x 12			
3		Floor Kitchen AC	12 x 12			
4		Floor Bedroom 3 BC	12 x 12			
5		Floor Bedroom 4 AC	12 x 12			
6		Floor Hallway 2 AC	12 x 12			
7		W-Si,, Bedroom 1 DC	15 x 2			
8		W-Si,, Kitchen BC	29 x 5 1/2			
9		W-Si,, Bedroom 3 CC	28 x 2 1/2			
10		W-Si,, Bedroom 4 AR	32 x 2 1/2			
			X			
			X			

Relinquished by: Yvonne Harding Signature: Yvonne Harding Date/Time: 09-12-24 11:00 AM

Received by: ELLEN STANTON Signature: _____ Date/Time: 9/16/24 127pm