



7469 Whitepine Rd
 North Chesterfield, VA 23237
 Telephone: 800.347.4010

Lead Dust Wipe Analysis Report

Report Number: 24-09-02612

Client: LEW Corp
 181 US Hwy 46
 Mine Hill, NJ 07803

Received Date: 09/16/2024
Analyzed Date: 09/18/2024
Reported Date: 09/19/2024

Project/Test Address: 77153; Dust Wipe Sampling; 649-51 East 6th St Unit 1; Plainfield, NJ

Collection Date: 09/12/2024

Client Number:
 201327

Laboratory Results

Fax Number:
 Ext 18 Melissa

| Lab Sample Number | Client Sample Number | Collection Location | Surface | Total Pb (ug) | Wipe Area (ft ²) | Concentration (ug/ft ²) | Narrative ID |
|-------------------|----------------------|----------------------|---------|---------------|------------------------------|-------------------------------------|--------------|
| 24-09-02612-001 | 1 | SUNROOM AC | FL | <5.00 | 1.00 | <5.00 | |
| 24-09-02612-002 | 2 | REAR ENTRY AC | FL | <5.00 | 1.00 | <5.00 | |
| 24-09-02612-003 | 3 | 2ND FLOOR HALLWAY AC | FL | <5.00 | 1.00 | <5.00 | |
| 24-09-02612-004 | 4 | BEDROOM 2 AC | FL | <5.00 | 1.00 | <5.00 | |
| 24-09-02612-005 | 5 | BEDROOM 4 AC | FL | <5.00 | 1.00 | <5.00 | |
| 24-09-02612-006 | 6 | 2ND FLOOR HALLWAY BC | SL | <5.00 | 0.521 | <9.60 | |
| 24-09-02612-007 | 7 | BEDROOM 2 DC | SL | 32.4 | 0.417 | 77.7 | |
| 24-09-02612-008 | 8 | BEDROOM 4 DC | SL | <5.00 | 0.417 | <12.0 | |
| 24-09-02612-009 | 9 | BEDROOM 1 DC | SL | <5.00 | 0.521 | <9.60 | |
| 24-09-02612-010 | 10 | BEDROOM 1 DC | FL | <5.00 | 1.00 | <5.00 | |

Environmental Hazards Services, L.L.C

Client Number: 201327

Report Number: 24-09-02612

Project/Test Address: 77153; Dust Wipe Sampling; 649-51 East 6th St Unit
1; Plainfield, NJ

| Lab Sample Number | Client Sample Number | Collection Location | Surface | Total Pb (ug) | Wipe Area (ft ²) | Concentration (ug/ft ²) | Narrative ID |
|-------------------|----------------------|---------------------|---------|---------------|------------------------------|-------------------------------------|--------------|
|-------------------|----------------------|---------------------|---------|---------------|------------------------------|-------------------------------------|--------------|

Method: ASTM E-1979-17/EPA SW846 7000B

Accreditation #:

Reviewed By Authorized Signatory: Melissa Kanode

Melissa Kanode

QA/QC Clerk

The Reporting Limit (RL) is 5.00 ug Total Pb. Dust wipe area and results are calculated based on area measurements determined by the client. All internal quality control requirements associated with this batch were met, unless otherwise noted.

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, etc., was provided by the client. Results reported above in ug/ft² are calculated based on area supplied by the client. If the report does not contain the result for a field blank, it is due to the fact that the client did not include a field blank with their samples. These sample results do not reflect blank correction. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C.

ELLAP Accreditation through AIHA LAP, LLC (100420), NY ELAP #11714.

| | | | |
|--------|-----------------|---|-----------|
| Legend | ug = microgram | ug/ft ² = micrograms per square foot | Pb = lead |
| | mL = milliliter | ft ² = square foot | |



ENVIRONMENTAL SERVICES

A Mainline Company


LEW Environmental Services P: (800) 783-0567

F: (908) 654-8069

Lead

Chain-of-Custody

24-09-02612



Due Date:

09/19/2024

(Thursday)

AE

* All wipes...

51

nts.

Project Name: Dust wipe Sampling
 Address: 649-51 East 6th St. Unit 1
 City, State: Plainfield, NJ
 Project Number: Order # 77153

Sample Type: Dust wipe Paint chip Soil TCLP

Turn Around Time (TAT): Same Day 3 Day 1 Day Weekend 1 Week 2 Weeks

Name: _____
 Signature: _____

Sampler Information

| Sample # | Date Collected | Sample Location (Ex: Fl, Kitchen, AC) | Area (inches) | Paint Chip Analysis | | |
|----------|----------------|--|------------------|---------------------|-----|------|
| | | | | mg/cm ² | PPM | % wt |
| 1 | 09-12-24 | Floor Sun Room AC | 12 x 12 | | | |
| 2 | | Floor Rear Entry AC | 12 x 12 | | | |
| 3 | | Floor 2nd floor Hallway AC | 12 x 12 | | | |
| 4 | | Floor Bedroom 2 AC | 12 x 12 | | | |
| 5 | | Floor Bedroom 4 AC | 12 x 12 | | | |
| 6 | | W-511 2nd floor Hallway BL | 30 x 2 1/2 | | | |
| 7 | | W-511 Bedroom 2 DC | 30 x 2 | | | |
| 8 | | W-511 Bedroom 4 DC | 30 x 2 | | | |
| 9 | | W-511 Bedroom 1 DC | 30 x 2 1/2 | | | |
| 10 | | Floor Bedroom 1 DC | 12 x 12 | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |

Relinquished by: Yvonne Fredia Signature: Yvonne Fredia Date/Time: 09-12-24 8:29am

Received by: DBrown Signature: DB Date/Time: 09/16/24 3:37pm