



7469 Whitepine Rd
North Chesterfield, VA 23237
Telephone: 800.347.4010

Lead Dust Wipe Analysis Report

Report Number: 24-11-02331

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Received Date: 11/13/2024
Analyzed Date: 11/15/2024
Reported Date: 11/18/2024

Project/Test Address: 79699; Lead Dust Wipe Sampling; 407 Firth St Unit 2; Phillipsburg, NJ

Collection Date: 11/11/2024

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft ²)	Concentration (ug/ft ²)	Narrative ID
24-11-02331-001	1	SUNROOM AC	FL	<5.00	1.00	<5.00	
24-11-02331-002	2	HALLWAY DC	FL	<5.00	1.00	<5.00	
24-11-02331-003	3	BEDROOM 1 AC	FL	<5.00	1.00	<5.00	
24-11-02331-004	4	BEDROOM 2 BC	FL	<5.00	1.00	<5.00	
24-11-02331-005	5	KTICHEN AC	FL	<5.00	1.00	<5.00	
24-11-02331-006	6	BATHROOM AC	FL	<5.00	1.00	<5.00	
24-11-02331-007	7	BEDROOM 1 AR	SL	<5.00	0.562	<8.90	
24-11-02331-008	8	BATHROOM BC	SL	<5.00	0.583	<8.58	
24-11-02331-009	9	BEDROOM 2 BC	SL	5.24	0.438	12.0	
24-11-02331-010	10	KITCHEN DC	SL	<5.00	0.153	<32.7	

Environmental Hazards Services, L.L.C

Client Number: 201327

Report Number: 24-11-02331

Project/Test Address: 79699; Lead Dust Wipe Sampling; 407 Firth St Unit 2;
Phillipsburg, NJ

Lab Sample Number	Client Sample Number	Collection Location	Surface	Total Pb (ug)	Wipe Area (ft ²)	Concentration (ug/ft ²)	Narrative ID
-------------------	----------------------	---------------------	---------	---------------	------------------------------	-------------------------------------	--------------

Method: ASTM E-1979-17/EPA SW846 7000B

Accreditation #:

Reviewed By Authorized Signatory: Melissa Kanode

Melissa Kanode

QA/QC Clerk

The Reporting Limit (RL) is 5.00 ug Total Pb. Dust wipe area and results are calculated based on area measurements determined by the client. All internal quality control requirements associated with this batch were met, unless otherwise noted.

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, etc., was provided by the client. Results reported above in ug/ft² are calculated based on area supplied by the client. If the report does not contain the result for a field blank, it is due to the fact that the client did not include a field blank with their samples. These sample results do not reflect blank correction. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, L.L.C.

ELLAP Accreditation through AIHA LAP, LLC (100420), NY ELAP #11714.

Legend	ug = microgram	ug/ft ² = micrograms per square foot	Pb = lead
	mL = milliliter	ft ² = square foot	



ENVIRONMENTAL SERVICES

A Mainline Company


LEW Environmental Services P: (800) 783-0567

F: (908) 654-8069

Lead

Chain-of-Custody

24-11-02331



Due Date:
11/18/2024
(Monday)
AE

* All wipes.

SA

Project Name: Lead dust wipe sampling
 Address: 402 Sixth St. unit 2
 City, State: Phillipsburg, NJ
 Project Number: Order # 79699

Sample Type
 Dust wipe
 Paint chip
 Soil
 TCLP

Turn Around Time (TAT)
 Same Day
 1 Day
 1 Week
 3 Day
 Weekend
 2 Weeks

Sampler Information
 Name: _____
 Signature: _____

Sample #	Date Collected	Sample Location (Ex: Fl, Kitchen, AC)	Area (inches)	Paint Chip Analysis		
				mg/cm ²	PPM	% wt
1	11-11-2024	Floor Sun Room AC	12 x 12			
2		Floor Hallway BC	12 x 12			
3		Floor Bedroom 1 AC	12 x 12			
4		Floor Bedroom 2 BC	12 x 12			
5		Floor Kitchen AC	12 x 12			
6		Floor Bathroom AC	12 x 12			
7		W-Sill Bedroom 1 AC	27 x 3			
8		W-Sill Bathroom BC	28 x 3			
9		W-Sill Bedroom 2 BC	21 x 3			
10		W-Sill Kitchen DC	22 x 1			

Relinquished by: Yvonne Hordia Signature: Yvonne Hordia Date/Time: 11-11-2024 9:10 am

Received by: Yvonne Signature: Yvonne Date/Time: 11/18/24 2:21 pm

108