

Company LEW Corporation
 XRF Make Heuresis
 Model Pb200i
 Serial Num. 1832
 Lead concentration units: mg/cm2
 Total Readings: 70
 Action Level 1
 Mode Action Level
 Analytic Mode Paint

All Readings

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location	Condition	Cause	
11221422	3760	0.9		TRUE	FALSE	11/22/2024	2:23 PM	Saheed Alex Adeyeri	Paint												
11221422	3761	0.9		TRUE	FALSE	11/22/2024	2:23 PM	Saheed Alex Adeyeri	Paint												
11221422	3762	0.9		TRUE	FALSE	11/22/2024	2:23 PM	Saheed Alex Adeyeri	Paint												
11221422	3763	-0.1		TRUE	FALSE	11/22/2024	2:24 PM	Saheed Alex Adeyeri	Paint												
11221422	3764	0		TRUE	FALSE	11/22/2024	2:24 PM	Saheed Alex Adeyeri	Paint												
11221422	3765	-0.1		TRUE	FALSE	11/22/2024	2:24 PM	Saheed Alex Adeyeri	Paint												
11221422	3766	0	Negative	FALSE	FALSE	11/22/2024	2:26 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		Living Room/Kitchen	Room	Wall	Drywall	A		Intact		
11221422	3767	-0.1	Negative	FALSE	FALSE	11/22/2024	2:26 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		Living Room/Kitchen	Room	Wall	Drywall	B		Intact		
11221422	3768	-0.1	Negative	FALSE	FALSE	11/22/2024	2:27 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		Living Room/Kitchen	Room	Wall	Drywall	C		Intact		
11221422	3769	0	Negative	FALSE	FALSE	11/22/2024	2:27 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		Living Room/Kitchen	Room	Wall	Drywall	D		Intact		
11221422	3770	0	Negative	FALSE	FALSE	11/22/2024	2:28 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		Living Room/Kitchen	Room	Ceiling	Drywall	D		Intact		
11221422	3771	0	Negative	FALSE	FALSE	11/22/2024	2:28 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		Living Room/Kitchen	Room	Floor	Wood	D		Intact		
11221422	3772	-0.1	Negative	FALSE	FALSE	11/22/2024	2:30 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		Living Room/Kitchen	Window	Sill	Wood	D		Intact		
11221422	3773	-0.1	Negative	FALSE	FALSE	11/22/2024	2:30 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		Living Room/Kitchen	Door	Casing	Wood	C		Intact		
11221422	3774	-0.1	Negative	FALSE	FALSE	11/22/2024	2:31 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		Living Room/Kitchen	Door	Jamb	Wood	C		Intact		
11221422	3775	0	Negative	FALSE	FALSE	11/22/2024	2:31 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		Living Room/Kitchen	Door	---	Wood	C		Intact		
11221422	3776	-0.1	Negative	FALSE	FALSE	11/22/2024	2:31 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		Living Room/Kitchen	Room	Baseboard	Wood	B		Intact		
11221422	3777	0	Negative	FALSE	FALSE	11/22/2024	2:32 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		Living Room/Kitchen	Stair	Stringer	Wood	B		Intact		
11221422	3778	0.1	Negative	FALSE	FALSE	11/22/2024	2:33 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		Living Room/Kitchen	Stair	Treads	Wood	B		Intact		
11221422	3779	0	Negative	FALSE	FALSE	11/22/2024	2:33 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		Living Room/Kitchen	Stair	Risers	Wood	B		Intact		
11221422	3780	-0.1	Negative	FALSE	FALSE	11/22/2024	2:33 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		Living Room/Kitchen	Stair	Newel Post	Wood	B		Intact		
11221422	3781	0	Negative	FALSE	FALSE	11/22/2024	2:33 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		Living Room/Kitchen	Stair	Railing	Wood	B		Intact		
11221422	3782	-0.1	Negative	FALSE	FALSE	11/22/2024	2:34 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		Living Room/Kitchen	Stair	Wall	Drywall	D		Intact		
11221422	3783	0	Negative	FALSE	FALSE	11/22/2024	2:35 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		1/2 Bathroom	Room	Wall	Drywall	A		Intact		
11221422	3784	0	Negative	FALSE	FALSE	11/22/2024	2:36 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		1/2 Bathroom	Room	Wall	Drywall	B		Intact		
11221422	3785	0	Negative	FALSE	FALSE	11/22/2024	2:36 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		1/2 Bathroom	Room	Wall	Drywall	C		Intact		
11221422	3786	0	Negative	FALSE	FALSE	11/22/2024	2:36 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		1/2 Bathroom	Room	Wall	Drywall	D		Intact		
11221422	3787	0	Negative	FALSE	FALSE	11/22/2024	2:38 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		1/2 Bathroom	Door	Casing	Wood	A		Intact		
11221422	3788	0	Negative	FALSE	FALSE	11/22/2024	2:38 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		1/2 Bathroom	Door	Jamb	Wood	A		Intact		
11221422	3789	-0.2	Negative	FALSE	FALSE	11/22/2024	2:38 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		1/2 Bathroom	Door	---	Wood	A		Intact		
11221422	3790	0	Negative	FALSE	FALSE	11/22/2024	2:41 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		Bedroom 1	Room	Wall	Drywall	A		Intact		
11221422	3791	-0.1	Negative	FALSE	FALSE	11/22/2024	2:41 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		Bedroom 1	Room	Wall	Drywall	B		Intact		
11221422	3792	-0.1	Negative	FALSE	FALSE	11/22/2024	2:42 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		Bedroom 1	Room	Wall	Drywall	C		Intact		
11221422	3793	0	Negative	FALSE	FALSE	11/22/2024	2:43 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		Bedroom 1	Room	Wall	Drywall	D		Intact		
11221422	3794	0.1	Negative	FALSE	FALSE	11/22/2024	2:43 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		Bedroom 1	Room	Ceiling	Drywall	D		Intact		
11221422	3795	-0.1	Negative	FALSE	FALSE	11/22/2024	2:43 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		Bedroom 1	Room	Baseboard	Wood	A		Intact		
11221422	3796	-0.1	Negative	FALSE	FALSE	11/22/2024	2:44 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		Bedroom 1	Door	Casing	Wood	A		Intact		
11221422	3797	0	Negative	FALSE	FALSE	11/22/2024	2:44 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		Bedroom 1	Door	Jamb	Wood	A		Intact		
11221422	3798	-0.3	Negative	FALSE	FALSE	11/22/2024	2:45 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		Bedroom 1	Door	---	Wood	A		Intact		
11221422	3799	0	Negative	FALSE	FALSE	11/22/2024	2:47 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		Bedroom 1	Window	Sill	Wood	C		Intact		
11221422	3800	0	Negative	FALSE	FALSE	11/22/2024	2:47 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		Bedroom 1	Closet	Door Casing	Wood	A		Intact		
11221422	3801	0	Negative	FALSE	FALSE	11/22/2024	2:48 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		Bedroom 1	Closet	Door Jamb	Wood	A		Intact		
11221422	3802	0.1	Negative	FALSE	FALSE	11/22/2024	2:48 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		Bedroom 1	Closet	Door	Wood	A		Intact		
11221422	3803	0.1	Negative	FALSE	FALSE	11/22/2024	2:49 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		Bedroom 2	Room	Wall	Drywall	A		Intact		
11221422	3804	0	Negative	FALSE	FALSE	11/22/2024	2:50 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		Bedroom 2	Room	Wall	Drywall	B		Intact		
11221422	3805	0	Negative	FALSE	FALSE	11/22/2024	2:50 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		Bedroom 2	Room	Wall	Drywall	C		Intact		
11221422	3806	0	Negative	FALSE	FALSE	11/22/2024	2:51 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		Bedroom 2	Room	Wall	Drywall	D		Intact		
11221422	3807	0.1	Negative	FALSE	FALSE	11/22/2024	2:51 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		Bedroom 2	Room	Ceiling	Drywall	D		Intact		
11221422	3808	-0.1	Negative	FALSE	FALSE	11/22/2024	2:52 PM	Saheed Alex Adeyeri	Paint	936 W 3rd Str	Unit		Bedroom 2	Window	Sill	Wood	D		Intact		

Company LEW Corporation
XRF Make Heuresis
Model Pb200i
Serial Num. 1832

Lead concentration units: mg/cm2

Total Readings: 70 Total Positives 0

Action Level 1

Mode Action Level

Analytic Mode Paint

Actionables

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location	Condition	Cause
No Actionables																				

Company LEW Corporation
XRF Make Heuresis
Model Pb200i
Serial Num. 1832

Lead concentration units: mg/cm2

Total Readings: 70 Total Hazards 0

Action Level 1

Mode Action Level

Analytic Mode Paint

Hazards

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location	Condition	Cause
No Hazards																				