

Company LEW Corporation  
 XRF Make Heuresis  
 Model Pb200i  
 Serial Num. 1832  
 Lead concentration units: mg/cm2  
 Total Readings: 68  
 Action Level 1  
 Mode Action Level  
 Analytic Mode Paint

All Readings

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location	Condition	Cause
11221017	3600	1.1		TRUE	FALSE	11/22/2024	10:17 AM	Saheed Alex Adeyeri	Paint											
11221017	3601	1		TRUE	FALSE	11/22/2024	10:18 AM	Saheed Alex Adeyeri	Paint											
11221017	3602	1.1		TRUE	FALSE	11/22/2024	10:18 AM	Saheed Alex Adeyeri	Paint											
11221017	3603	0		TRUE	FALSE	11/22/2024	10:18 AM	Saheed Alex Adeyeri	Paint											
11221017	3604	0		TRUE	FALSE	11/22/2024	10:18 AM	Saheed Alex Adeyeri	Paint											
11221017	3605	0		TRUE	FALSE	11/22/2024	10:18 AM	Saheed Alex Adeyeri	Paint											
11221017	3606	0.2	Negative	FALSE	FALSE	11/22/2024	10:20 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		Living Room/Dining Room	Room	Wall	Drywall	A		Intact	
11221017	3607	0	Negative	FALSE	FALSE	11/22/2024	10:21 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		Living Room/Dining Room	Room	Wall	Drywall	B		Intact	
11221017	3608	0	Negative	FALSE	FALSE	11/22/2024	10:21 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		Living Room/Dining Room	Room	Wall	Drywall	C		Intact	
11221017	3609	0.1	Negative	FALSE	FALSE	11/22/2024	10:21 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		Living Room/Dining Room	Room	Wall	Drywall	D		Intact	
11221017	3610	-0.1	Negative	FALSE	FALSE	11/22/2024	10:22 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		Living Room/Dining Room	Room	Ceiling	Drywall	D		Intact	
11221017	3611	0	Negative	FALSE	FALSE	11/22/2024	10:22 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		Living Room/Dining Room	Room	Floor	Wood	D		Intact	
11221017	3612	0.5	Negative	FALSE	FALSE	11/22/2024	10:23 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		Living Room/Dining Room	Window	Casing	Wood	D		Intact	
11221017	3613	0.5	Negative	FALSE	FALSE	11/22/2024	10:23 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		Living Room/Dining Room	Window	Jamb	Wood	D		Intact	
11221017	3614	0.6	Negative	FALSE	FALSE	11/22/2024	10:23 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		Living Room/Dining Room	Window	Sill	Wood	D		Intact	
11221017	3615	0	Negative	FALSE	FALSE	11/22/2024	10:24 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		Living Room/Dining Room	Door	Casing	Wood	A		Intact	
11221017	3616	-0.2	Negative	FALSE	FALSE	11/22/2024	10:25 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		Living Room/Dining Room	Door	Jamb	Wood	A		Intact	
11221017	3617	0.1	Negative	FALSE	FALSE	11/22/2024	10:25 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		Living Room/Dining Room	Door	---	Wood	A		Intact	
11221017	3618	0.6	Negative	FALSE	FALSE	11/22/2024	10:25 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		Living Room/Dining Room	Room	Baseboard	Wood	A		Intact	
11221017	3619	-0.1	Negative	FALSE	FALSE	11/22/2024	10:26 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		Living Room/Dining Room	Stair	Balusters	Wood	A		Intact	
11221017	3620	-0.3	Negative	FALSE	FALSE	11/22/2024	10:26 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		Living Room/Dining Room	Stair	Newel Post	Wood	A		Intact	
11221017	3621	0.5	Negative	FALSE	FALSE	11/22/2024	10:27 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		Living Room/Dining Room	Stair	Wall	Drywall	A		Intact	
11221017	3622	0	Negative	FALSE	FALSE	11/22/2024	10:28 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		Kitchen	Room	Wall	Drywall	A		Intact	
11221017	3623	-0.1	Negative	FALSE	FALSE	11/22/2024	10:28 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		Kitchen	Room	Wall	Drywall	B		Intact	
11221017	3624	0	Negative	FALSE	FALSE	11/22/2024	10:28 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		Kitchen	Room	Wall	Drywall	C		Intact	
11221017	3625	0	Negative	FALSE	FALSE	11/22/2024	10:29 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		Kitchen	Room	Wall	Drywall	D		Intact	
11221017	3626	0.1	Negative	FALSE	FALSE	11/22/2024	10:38 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		Kitchen	Room	Ceiling	Drywall	D		Intact	
11221017	3627	-0.1	Negative	FALSE	FALSE	11/22/2024	10:39 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		Kitchen	Door	Casing	Wood	C		Intact	
11221017	3628	-0.1	Negative	FALSE	FALSE	11/22/2024	10:39 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		Kitchen	Door	Jamb	Wood	C		Intact	
11221017	3629	0.1	Negative	FALSE	FALSE	11/22/2024	10:39 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		Kitchen	Door	---	Wood	C		Intact	
11221017	3630	-0.1	Negative	FALSE	FALSE	11/22/2024	10:40 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		Kitchen	Closet	Door Casing	Wood	A		Intact	
11221017	3631	0.1	Negative	FALSE	FALSE	11/22/2024	10:40 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		Kitchen	Closet	Door Jamb	Wood	A		Intact	
11221017	3632	0.1	Negative	FALSE	FALSE	11/22/2024	10:41 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		Kitchen	Closet	Door	Wood	A		Intact	
11221017	3633	-0.1	Negative	FALSE	FALSE	11/22/2024	10:42 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		Kitchen	Closet	Shelf Support	Wood	A		Intact	
11221017	3634	-0.1	Negative	FALSE	FALSE	11/22/2024	10:42 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		Kitchen	Closet	Shelf	Wood	A		Intact	
11221017	3635	-0.1	Negative	FALSE	FALSE	11/22/2024	10:43 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		1/2 Bathroom	Room	Wall	Drywall	A		Intact	
11221017	3636	0.1	Negative	FALSE	FALSE	11/22/2024	10:44 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		1/2 Bathroom	Room	Wall	Drywall	B		Intact	
11221017	3637	0	Negative	FALSE	FALSE	11/22/2024	10:44 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		1/2 Bathroom	Room	Wall	Drywall	C		Intact	
11221017	3638	0	Negative	FALSE	FALSE	11/22/2024	10:44 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		1/2 Bathroom	Room	Wall	Drywall	D		Intact	
11221017	3639	0	Negative	FALSE	FALSE	11/22/2024	10:45 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		1/2 Bathroom	Room	Ceiling	Drywall	D		Intact	
11221017	3640	0.1	Negative	FALSE	FALSE	11/22/2024	10:45 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		1/2 Bathroom	Door	Casing	Wood	B		Intact	
11221017	3641	-0.1	Negative	FALSE	FALSE	11/22/2024	10:45 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		1/2 Bathroom	Door	Jamb	Wood	B		Intact	
11221017	3642	-0.2	Negative	FALSE	FALSE	11/22/2024	10:45 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		1/2 Bathroom	Door	---	Wood	B		Intact	
11221017	3643	0	Negative	FALSE	FALSE	11/22/2024	10:51 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		Bathroom 1	Room	Wall	Drywall	A		Intact	
11221017	3644	0	Negative	FALSE	FALSE	11/22/2024	10:52 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		Bathroom 1	Room	Wall	Drywall	B		Intact	
11221017	3645	0	Negative	FALSE	FALSE	11/22/2024	10:52 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		Bathroom 1	Room	Wall	Drywall	C		Intact	
11221017	3646	0	Negative	FALSE	FALSE	11/22/2024	10:52 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		Bathroom 1	Room	Wall	Drywall	D		Intact	
11221017	3647	0	Negative	FALSE	FALSE	11/22/2024	10:52 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		Bathroom 1	Room	Ceiling	Drywall	D		Intact	
11221017	3648	0.4	Negative	FALSE	FALSE	11/22/2024	10:53 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		Bathroom 1	Window	Casing	Wood	A		Intact	
11221017	3649	0.3	Negative	FALSE	FALSE	11/22/2024	10:53 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		Bathroom 1	Window	Jamb	Wood	A		Intact	
11221017	3650	0.1	Negative	FALSE	FALSE	11/22/2024	10:54 AM	Saheed Alex Adeyeri	Paint	731 E 3rd Str	Unit		Bathroom 1	Window	Sill	Wood	A		Intact	



Company LEW Corporation  
XRF Make Heuresis  
Model Pb200i  
Serial Num. 1832

Lead concentration units: mg/cm2

Total Readings: 68 Total Positives 0

Action Level 1

Mode Action Level

Analytic Mode Paint

### Actionables

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location	Condition	Cause
No Actionables																				

Company LEW Corporation  
XRF Make Heuresis  
Model Pb200i  
Serial Num. 1832

Lead concentration units: mg/cm2

Total Readings: 68 Total Hazards 0

Action Level 1

Mode Action Level

Analytic Mode Paint

### Hazards

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location	Condition	Cause
No Hazards																				