

Company LEW Corporation
 XRF Make Heuresis
 Model Pb200i
 Serial Num. 2819

Lead concentration units: mg/cm2
 Total Readings: 154
 Action Level 1
 Mode Action Level
 Analytic Mode Paint

All Readings

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location	Condition	Cause
9111321	54839	1.1		TRUE	FALSE	9/11/2024	1:23 PM	Yerani Heredia	Paint	63 Vernoy Rd.										
9111321	54840	1.1		TRUE	FALSE	9/11/2024	1:24 PM	Yerani Heredia	Paint	63 Vernoy Rd.										
9111321	54841	1.2		TRUE	FALSE	9/11/2024	1:24 PM	Yerani Heredia	Paint	63 Vernoy Rd.										
9111321	54842	0		TRUE	FALSE	9/11/2024	1:25 PM	Yerani Heredia	Paint	63 Vernoy Rd.										
9111321	54843	0		TRUE	FALSE	9/11/2024	1:26 PM	Yerani Heredia	Paint	63 Vernoy Rd.										
9111321	54844	0		TRUE	FALSE	9/11/2024	1:26 PM	Yerani Heredia	Paint	63 Vernoy Rd.										
9111321	54845	0.1	Negative	FALSE	FALSE	9/11/2024	1:27 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Living Room/Kitchen	Door	---	Wood	A	1	Intact	
9111321	54846	0	Negative	FALSE	FALSE	9/11/2024	1:28 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Living Room/Kitchen	Door	Jamb	Wood	A	1	Intact	
9111321	54847	0.1	Negative	FALSE	FALSE	9/11/2024	1:28 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Living Room/Kitchen	Door	Casing	Wood	A	1	Intact	
9111321	54848	0.1	Negative	FALSE	FALSE	9/11/2024	1:29 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Living Room/Kitchen	Room	Wall	Plaster	A	1	Intact	
9111321	54849	0.1	Negative	FALSE	FALSE	9/11/2024	1:30 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Living Room/Kitchen	Room	Wall	Plaster	B	1	Intact	
9111321	54850	0.1	Negative	FALSE	FALSE	9/11/2024	1:31 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Living Room/Kitchen	Room	Wall	Plaster	C	1	Intact	
9111321	54851	-0.2	Negative	FALSE	FALSE	9/11/2024	1:31 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Living Room/Kitchen	Room	Wall	Plaster	D	1	Intact	
9111321	54852	0.1	Negative	FALSE	FALSE	9/11/2024	1:32 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Living Room/Kitchen	Room	Baseboard	Wood	D	1	Intact	
9111321	54853	-0.2	Negative	FALSE	FALSE	9/11/2024	1:32 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Living Room/Kitchen	Closet	Door	Wood	D	1	Intact	
9111321	54854	0	Negative	FALSE	FALSE	9/11/2024	1:33 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Living Room/Kitchen	Closet	Door Jamb	Wood	D	1	Intact	
9111321	54855	0.1	Negative	FALSE	FALSE	9/11/2024	1:35 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Living Room/Kitchen	Closet	Door Casing	Wood	D	1	Intact	
9111321	54856	0.2	Negative	FALSE	FALSE	9/11/2024	1:36 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Living Room/Kitchen	Closet	Wall	Plaster	D	1	Intact	
9111321	54857	-0.1	Negative	FALSE	FALSE	9/11/2024	1:36 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Living Room/Kitchen	Closet	Baseboard	Wood	D	1	Intact	
9111321	54858	-0.1	Negative	FALSE	FALSE	9/11/2024	1:37 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Living Room/Kitchen	Window	Casing	Wood	C	1	Intact	
9111321	54859	-0.1	Negative	FALSE	FALSE	9/11/2024	1:38 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Living Room/Kitchen	Window	Sash	Wood	C	1	Intact	
9111321	54860	0.1	Negative	FALSE	FALSE	9/11/2024	1:38 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Living Room/Kitchen	Window	Sill	Wood	C	1	Intact	
9111321	54861	-0.3	Negative	FALSE	FALSE	9/11/2024	1:39 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Living Room/Kitchen	Stair	Risers	Wood	D	1	Intact	
9111321	54862	0	Negative	FALSE	FALSE	9/11/2024	1:39 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Living Room/Kitchen	Stair	Stringer	Wood	D	1	Intact	
9111321	54863	-0.1	Negative	FALSE	FALSE	9/11/2024	1:40 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Living Room/Kitchen	Stair	Balusters	Wood	D	1	Intact	
9111321	54864	-0.3	Negative	FALSE	FALSE	9/11/2024	1:41 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Living Room/Kitchen	Room	Ceiling	Drywall	D	1	Intact	
9111321	54865	0	Negative	FALSE	FALSE	9/11/2024	1:41 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Living Room/Kitchen	Door	---	Wood	C	1	Intact	
9111321	54866	-0.1	Negative	FALSE	FALSE	9/11/2024	1:42 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Living Room/Kitchen	Door	Casing	Wood	C	1	Intact	
9111321	54867	-0.1	Negative	FALSE	FALSE	9/11/2024	1:42 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Living Room/Kitchen	Door	Jamb	Wood	C	1	Intact	
9111321	54868	-0.3	Negative	FALSE	FALSE	9/11/2024	1:43 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Side Entry	Door	Casing	Wood	D	1	Intact	
9111321	54869	-0.2	Negative	FALSE	FALSE	9/11/2024	1:44 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Side Entry	Door	Casing	Wood	A	1	Intact	
9111321	54870	0.1	Negative	FALSE	FALSE	9/11/2024	1:44 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Side Entry	Door	---	Wood	A	1	Intact	
9111321	54871	0.1	Negative	FALSE	FALSE	9/11/2024	1:45 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Side Entry	Door	Jamb	Wood	A	1	Intact	
9111321	54872	0.1	Negative	FALSE	FALSE	9/11/2024	1:47 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Side Entry	Room	Wall	Plaster	B	1	Intact	
9111321	54873	0.1	Negative	FALSE	FALSE	9/11/2024	1:48 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Side Entry	Room	Wall	Plaster	C	1	Intact	
9111321	54874	0.1	Negative	FALSE	FALSE	9/11/2024	1:48 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Side Entry	Room	Wall	Plaster	D	1	Intact	
9111321	54875	0	Negative	FALSE	FALSE	9/11/2024	1:49 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Side Entry	Room	Baseboard	Wood	D	1	Intact	
9111321	54876	-0.2	Negative	FALSE	FALSE	9/11/2024	1:50 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Side Entry	Closet	Door	Wood	C	1	Intact	
9111321	54877	0.1	Negative	FALSE	FALSE	9/11/2024	1:50 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Side Entry	Closet	Door Jamb	Wood	C	1	Intact	
9111321	54878	0	Negative	FALSE	FALSE	9/11/2024	1:51 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Side Entry	Closet	Door Casing	Wood	C	1	Intact	
9111321	54879	0.1	Negative	FALSE	FALSE	9/11/2024	1:52 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Side Entry	Closet	Door	Drywall	C	1	Intact	
9111321	54880	0	Negative	FALSE	FALSE	9/11/2024	1:53 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Side Entry	Closet	Wall	Drywall	C	1	Intact	
9111321	54881	-0.1	Negative	FALSE	FALSE	9/11/2024	1:53 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Side Entry	Closet	Shelf	Drywall	C	1	Intact	
9111321	54882	0	Negative	FALSE	FALSE	9/11/2024	1:54 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Side Entry	Closet	Baseboard	Wood	C	1	Intact	
9111321	54883	0	Negative	FALSE	FALSE	9/11/2024	1:55 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bathroom	Door	---	Wood	B	1	Intact	
9111321	54884	-0.1	Negative	FALSE	FALSE	9/11/2024	1:55 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bathroom	Door	Casing	Wood	B	1	Intact	

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location	Condition	Cause
9111321	54885	0	Negative	FALSE	FALSE	9/11/2024	1:56 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bathroom	Room	Wall	Wood	A	1	Intact	
9111321	54886	0.1	Negative	FALSE	FALSE	9/11/2024	1:57 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bathroom	Room	Wall	Wood	B	1	Intact	
9111321	54887	0.1	Negative	FALSE	FALSE	9/11/2024	1:57 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bathroom	Room	Wall	Wood	D	1	Intact	
9111321	54888	0.1	Negative	FALSE	FALSE	9/11/2024	1:58 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bathroom	Room	Baseboard	Wood	D	1	Intact	
9111321	54889	-0.1	Negative	FALSE	FALSE	9/11/2024	1:58 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bathroom	Window	Sash	Wood	D	1	Intact	
9111321	54890	0.1	Negative	FALSE	FALSE	9/11/2024	1:59 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bathroom	Window	Casing	Wood	D	1	Intact	
9111321	54891	-0.1	Negative	FALSE	FALSE	9/11/2024	2:00 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bathroom	Window	Sill	Wood	D	1	Intact	
9111321	54892	0.1	Negative	FALSE	FALSE	9/11/2024	2:00 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bathroom	Room	Wall	Wood	D	2	Intact	
9111321	54893	0.1	Negative	FALSE	FALSE	9/11/2024	2:01 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bathroom	Room	Wall	Wood	C	2	Intact	
9111321	54894	0.1	Negative	FALSE	FALSE	9/11/2024	2:02 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bedroom 1	Door	---	Wood	C	1	Intact	
9111321	54895	0.2	Negative	FALSE	FALSE	9/11/2024	2:04 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bedroom 1	Door	Jamb	Wood	C	1	Intact	
9111321	54896	-0.2	Negative	FALSE	FALSE	9/11/2024	2:05 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bedroom 1	Door	Casing	Wood	C	1	Intact	
9111321	54897	0	Negative	FALSE	FALSE	9/11/2024	2:05 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bedroom 1	Room	Baseboard	Wood	C	1	Intact	
9111321	54898	0.1	Negative	FALSE	FALSE	9/11/2024	2:06 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bedroom 1	Room	Wall	Plaster	B	1	Intact	
9111321	54899	0.2	Negative	FALSE	FALSE	9/11/2024	2:07 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bedroom 1	Room	Wall	Plaster	A	1	Intact	
9111321	54900	0.1	Negative	FALSE	FALSE	9/11/2024	2:08 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bedroom 1	Room	Wall	Plaster	D	1	Intact	
9111321	54901	0.2	Negative	FALSE	FALSE	9/11/2024	2:09 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bedroom 1	Room	Wall	Plaster	C	1	Intact	
9111321	54902	0.1	Negative	FALSE	FALSE	9/11/2024	2:10 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bedroom 1	Closet	Door	Wood	C	1	Intact	
9111321	54903	-0.1	Negative	FALSE	FALSE	9/11/2024	2:10 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bedroom 1	Closet	Door Casing	Wood	C	1	Intact	
9111321	54904	-0.1	Negative	FALSE	FALSE	9/11/2024	2:11 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bedroom 1	Window	Sash	Wood	A	1	Intact	
9111321	54905	0	Negative	FALSE	FALSE	9/11/2024	2:12 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bedroom 1	Window	Casing	Wood	A	1	Intact	
9111321	54906	0	Negative	FALSE	FALSE	9/11/2024	2:12 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bedroom 1	Window	Sill	Wood	A	1	Intact	
9111321	54907	-0.1	Negative	FALSE	FALSE	9/11/2024	2:13 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bedroom 1	Window	Apron	Wood	A	1	Intact	
9111321	54908	0.1	Negative	FALSE	FALSE	9/11/2024	2:13 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bedroom 1	Window	Jamb	Wood	A	1	Intact	
9111321	54909	0.1	Negative	FALSE	FALSE	9/11/2024	2:17 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Basement Stairwell	Door	---	Wood	C	1	Intact	
9111321	54910	0.1	Negative	FALSE	FALSE	9/11/2024	2:18 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Basement Stairwell	Door	Jamb	Wood	C	1	Intact	
9111321	54911	-0.1	Negative	FALSE	FALSE	9/11/2024	2:18 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Basement Stairwell	Door	Casing	Wood	C	1	Intact	
9111321	54912	0.1	Negative	FALSE	FALSE	9/11/2024	2:19 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Basement Stairwell	Room	Wall	Plaster	C	1	Intact	
9111321	54913	0.1	Negative	FALSE	FALSE	9/11/2024	2:20 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Basement Stairwell	Room	Wall	Plaster	B	1	Intact	
9111321	54914	0	Negative	FALSE	FALSE	9/11/2024	2:20 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Basement Stairwell	Room	Wall	Plaster	A	1	Intact	
9111321	54915	-0.2	Negative	FALSE	FALSE	9/11/2024	2:21 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Basement Stairwell	Room	Wall	Plaster	D	1	Intact	
9111321	54916	0	Negative	FALSE	FALSE	9/11/2024	2:21 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Basement Stairwell	Room	Ceiling	Plaster	D	1	Intact	
9111321	54917	-0.2	Negative	FALSE	FALSE	9/11/2024	2:22 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Basement Stairwell	Stair	Risers	Wood	D	1	Intact	
9111321	54918	-0.1	Negative	FALSE	FALSE	9/11/2024	2:23 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Basement Stairwell	Stair	Stringer	Wood	D	1	Intact	
9111321	54919	-0.1	Negative	FALSE	FALSE	9/11/2024	2:23 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Basement Stairwell	Stair	Balusters	Wood	D	1	Intact	
9111321	54920	0	Negative	FALSE	FALSE	9/11/2024	2:24 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	2nd Floor Hallway	Room	Wall	Wood	D	1	Intact	
9111321	54921	0.1	Negative	FALSE	FALSE	9/11/2024	2:25 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	2nd Floor Hallway	Room	Wall	Wood	C	1	Intact	
9111321	54922	-0.1	Negative	FALSE	FALSE	9/11/2024	2:25 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	2nd Floor Hallway	Room	Wall	Wood	B	1	Intact	
9111321	54923	0	Negative	FALSE	FALSE	9/11/2024	2:26 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	2nd Floor Hallway	Room	Baseboard	Wood	B	1	Intact	
9111321	54924	0	Negative	FALSE	FALSE	9/11/2024	2:27 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	2nd Floor Hallway	Room	Ceiling	Wood	B	1	Intact	
9111321	54925	0.1	Negative	FALSE	FALSE	9/11/2024	2:27 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bedroom 2	Door	---	Wood	D	1	Intact	
9111321	54926	0	Negative	FALSE	FALSE	9/11/2024	2:28 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bedroom 2	Door	Jamb	Wood	D	1	Intact	
9111321	54927	0	Negative	FALSE	FALSE	9/11/2024	2:29 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bedroom 2	Door	Casing	Wood	D	1	Intact	
9111321	54928	0	Negative	FALSE	FALSE	9/11/2024	2:29 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bedroom 2	Room	Wall	Plaster	A	1	Intact	
9111321	54929	0.1	Negative	FALSE	FALSE	9/11/2024	2:30 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bedroom 2	Room	Wall	Plaster	B	1	Intact	
9111321	54930	0.1	Negative	FALSE	FALSE	9/11/2024	2:30 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bedroom 2	Room	Wall	Plaster	C	1	Intact	
9111321	54931	-0.1	Negative	FALSE	FALSE	9/11/2024	2:31 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bedroom 2	Room	Wall	Plaster	D	1	Intact	
9111321	54932	0.1	Negative	FALSE	FALSE	9/11/2024	2:32 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bedroom 2	Room	Baseboard	Wood	D	1	Intact	
9111321	54933	0	Negative	FALSE	FALSE	9/11/2024	2:33 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bedroom 2	Window	Sash	Wood	A	1	Intact	
9111321	54934	-0.1	Negative	FALSE	FALSE	9/11/2024	2:33 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bedroom 2	Window	Casing	Wood	A	1	Intact	
9111321	54935	-0.1	Negative	FALSE	FALSE	9/11/2024	2:34 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bedroom 2	Window	Jamb	Wood	A	1	Intact	
9111321	54936	0.1	Negative	FALSE	FALSE	9/11/2024	2:34 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bedroom 2	Window	Casing	Wood	A	1	Intact	
9111321	54937	0.1	Negative	FALSE	FALSE	9/11/2024	2:35 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bedroom 2	Window	Sill	Wood	A	1	Intact	
9111321	54938	0	Negative	FALSE	FALSE	9/11/2024	2:35 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bedroom 2	Closet	Door	Wood	B	1	Intact	
9111321	54939	0	Negative	FALSE	FALSE	9/11/2024	2:36 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bedroom 2	Closet	Door Buck	Wood	B	1	Intact	
9111321	54940	0	Negative	FALSE	FALSE	9/11/2024	2:37 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bedroom 2	Closet	Wall	Plaster	B	1	Intact	
9111321	54941	0	Negative	FALSE	FALSE	9/11/2024	2:37 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bedroom 2	Closet	Baseboard	Wood	B	1	Intact	
9111321	54942	0.1	Negative	FALSE	FALSE	9/11/2024	2:38 PM	Yerani Heredia	Paint	63 Vernoy Rd.	Unit	1	Bedroom 2	Closet	Shelf	Wood	B	1	Intact	

Company LEW Corporation
XRF Make Heuresis
Model Pb200i
Serial Num. 2819

Lead concentration units: mg/cm2
Total Readings: 154 Total Positives 0
Action Level 1
Mode Action Level
Analytic Mode Paint

Actionables

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location	Condition	Cause
No Actionables																				

Company LEW Corporation
XRF Make Heuresis
Model Pb200i
Serial Num. 2819

Lead concentration units: mg/cm2
Total Readings: 154 Total Hazards 0
Action Level 1
Mode Action Level
Analytic Mode Paint

Hazards

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location	Condition	Cause
No Hazards																				