

Company LEW Corporation
 XRF Make Heuresis
 Model Pb200i
 Serial Num. 1833
 Lead concentration units: mg/cm2
 Total Readings: 48
 Action Level 1
 Mode Action Level
 Analytic Mode Lead Paint

All Readings

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
1916 Whitcomb	24709	0.1	Negative	FALSE	FALSE	9/24/2024	3:23 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Living Room	Window	Casing	Wood	D	1
1916 Whitcomb	24710	0.1	Negative	FALSE	FALSE	9/24/2024	3:24 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Living Room	Window	Sill	Wood	A	1
1916 Whitcomb	24711	0.1	Negative	FALSE	FALSE	9/24/2024	3:25 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Living Room	Closet	Door	Wood	D	1
1916 Whitcomb	24712	0.1	Negative	FALSE	FALSE	9/24/2024	3:25 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Living Room	Closet	Door Casing	Wood	D	1
1916 Whitcomb	24713	0	Negative	FALSE	FALSE	9/24/2024	3:26 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Living Room	Closet	Shelf Support	Wood	D	1
1916 Whitcomb	24714	0.1	Negative	FALSE	FALSE	9/24/2024	3:27 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Living Room	Door	---	Wood	A	1
1916 Whitcomb	24715	0	Negative	FALSE	FALSE	9/24/2024	3:28 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Living Room	Door	Casing	Wood	A	1
1916 Whitcomb	24716	0.1	Negative	FALSE	FALSE	9/24/2024	3:29 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Living Room	Room	Ceiling	Drywall	A	1
1916 Whitcomb	24717	0.1	Negative	FALSE	FALSE	9/24/2024	3:29 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Living Room	Room	Wall	Drywall	A	1
1916 Whitcomb	24718	0.1	Negative	FALSE	FALSE	9/24/2024	3:30 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Living Room	Room	Wall	Drywall	D	1
1916 Whitcomb	24719	0.1	Negative	FALSE	FALSE	9/24/2024	3:31 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Living Room	Room	Wall	Drywall	C	1
1916 Whitcomb	24720	0.2	Negative	FALSE	FALSE	9/24/2024	3:32 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Living Room	Room	Wall	Drywall	B	1
1916 Whitcomb	24721	0.1	Negative	FALSE	FALSE	9/24/2024	3:33 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Living Room	Room	Baseboard	Wood	B	1
1916 Whitcomb	24722	0.1	Negative	FALSE	FALSE	9/24/2024	3:34 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Kitchen	Room	Baseboard	Wood	B	1
1916 Whitcomb	24723	0.1	Negative	FALSE	FALSE	9/24/2024	3:35 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Kitchen	Door	Casing	Wood	B	1
1916 Whitcomb	24724	0.1	Negative	FALSE	FALSE	9/24/2024	3:36 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Kitchen	Door	---	Wood	B	1
1916 Whitcomb	24725	0.1	Negative	FALSE	FALSE	9/24/2024	3:37 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Kitchen	Window	Sill	Wood	B	1
1916 Whitcomb	24726	0.1	Negative	FALSE	FALSE	9/24/2024	3:38 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Kitchen	Window	Casing	Wood	B	1
1916 Whitcomb	24727	0.2	Negative	FALSE	FALSE	9/24/2024	3:39 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Kitchen	Room	Ceiling	Wood	B	1
1916 Whitcomb	24728	0.2	Negative	FALSE	FALSE	9/24/2024	3:40 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Kitchen	Room	Wall	Wood	A	1
1916 Whitcomb	24729	0	Negative	FALSE	FALSE	9/24/2024	3:40 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Kitchen	Room	Wall	Wood	D	1
1916 Whitcomb	24730	0.3	Negative	FALSE	FALSE	9/24/2024	3:41 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Kitchen	Room	Wall	Wood	C	1
1916 Whitcomb	24731	0	Negative	FALSE	FALSE	9/24/2024	3:42 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Bathroom	Door	---	Wood	C	1
1916 Whitcomb	24732	0.2	Negative	FALSE	FALSE	9/24/2024	3:43 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Bathroom	Door	Jamb	Wood	C	1
1916 Whitcomb	24733	0.1	Negative	FALSE	FALSE	9/24/2024	3:43 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Bathroom	Door	Casing	Wood	C	1
1916 Whitcomb	24734	0.1	Negative	FALSE	FALSE	9/24/2024	3:44 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Bathroom	Window	Casing	Wood	C	1
1916 Whitcomb	24735	0.2	Negative	FALSE	FALSE	9/24/2024	3:45 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Bathroom	Room	Wall	Drywall	B	1
1916 Whitcomb	24736	0.1	Negative	FALSE	FALSE	9/24/2024	3:45 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Bathroom	Room	Wall	Drywall	A	1
1916 Whitcomb	24737	0.1	Negative	FALSE	FALSE	9/24/2024	3:46 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Bathroom	Room	Wall	Drywall	D	1
1916 Whitcomb	24738	0.2	Negative	FALSE	FALSE	9/24/2024	3:47 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Bathroom	Room	Wall	Drywall	C	1
1916 Whitcomb	24739	0.2	Negative	FALSE	FALSE	9/24/2024	3:48 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Bedroom 1	Room	Wall	Drywall	A	1
1916 Whitcomb	24740	0	Negative	FALSE	FALSE	9/24/2024	3:48 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Bedroom 1	Room	Wall	Drywall	B	1
1916 Whitcomb	24741	0.1	Negative	FALSE	FALSE	9/24/2024	3:49 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Bedroom 1	Room	Wall	Drywall	C	1
1916 Whitcomb	24742	0.2	Negative	FALSE	FALSE	9/24/2024	3:50 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Bedroom 1	Room	Wall	Drywall	D	1
1916 Whitcomb	24743	0	Negative	FALSE	FALSE	9/24/2024	3:51 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Bedroom 1	Window	Casing	Wood	C	1
1916 Whitcomb	24744	0	Negative	FALSE	FALSE	9/24/2024	3:51 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Bedroom 1	Window	Sill	Wood	C	1
1916 Whitcomb	24745	0.2	Negative	FALSE	FALSE	9/24/2024	3:52 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Bedroom 1	Window	Sash	Wood	C	1
1916 Whitcomb	24746	0.1	Negative	FALSE	FALSE	9/24/2024	3:53 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Bedroom 1	Door	---	Wood	B	1
1916 Whitcomb	24747	0.1	Negative	FALSE	FALSE	9/24/2024	3:54 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Bedroom 1	Door	Jamb	Wood	B	1
1916 Whitcomb	24748	0	Negative	FALSE	FALSE	9/24/2024	3:55 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Bedroom 1	Door	Casing	Wood	B	1
1916 Whitcomb	24749	0.1	Negative	FALSE	FALSE	9/24/2024	3:56 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Bedroom 2	Door	Casing	Wood	C	1
1916 Whitcomb	24750	0.1	Negative	FALSE	FALSE	9/24/2024	3:56 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Bedroom 2	Door	Jamb	Wood	C	1
1916 Whitcomb	24752	0	Negative	FALSE	FALSE	9/24/2024	3:58 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Bedroom 2	Window	Sash	Wood	C	1
1916 Whitcomb	24753	0.1	Negative	FALSE	FALSE	9/24/2024	3:59 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Bedroom 2	Window	Sash	Wood	C	1
1916 Whitcomb	24755	0.1	Negative	FALSE	FALSE	9/24/2024	4:01 PM	Nyire Edmonds-Grant	Lead Paint	1916 Whitcomb Road	Unit	Main	Bedroom 2	Room	Wall	Drywall	C	1

Company LEW Corporation
XRF Make Heuresis
Model Pb200i
Serial Num. 1833

Lead concentration units: mg/cm2

Total Readings: 48 Total Positives 0

Action Level 1

Mode Action Level

Analytic Mode Lead Paint

Actionables

Job Id	Reading #	Concentration	Result	Calibration	RTA Present	Date	Time	User	Analytic Mode	Site Address	Area	Unit #	Room	Structure	Member	Substrate	Wall	Location
No Actionables																		